

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

70.0

35.0

1.3

1.8

3.7

6.2

N/A

Good N/A

Intersection ID: 42582 Main Street: COLLEGE-TRYON_ST Cross Street: N_TRYON_ST Location: NW

ADA ID: 8799CC925047 Ramp Type: Combination1 Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 42.5

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

Compliance Description

Data

N/A

N/A

N/A

N/A

Yes

Clear Space to XWalk (in)

Storm Grate/Utility Hazard?

Storm Grate/Utility Type

Surface Condition? (G/P)

Any Obstruction?

Obstruction Type

Curb Slope (%)



Street 1 Name

Stop Condition-Street 1

N TRYON ST

Street 2 Name

N/A

Stop Condition-Street 2

N/A

Possible Solutions:

Remove & Replace Entire Ramp.

N/A Ramp Length LT (in)
No Ramp Width LT (in)
No Ramp Slope LT (%)
Yes Ramp XSlope LT (%)
N/A Ramp Length (in)
Yes Ramp Width (in)
Surveyor Notes:

RT RP < 5%

N/A Flare Type LT


RT RP < 5%

N/A Flare Slope LT (%)
N/A Landing Length (in)
N/A Landing Width (in)
PROW/ADA:

R304.5.1, R304.5.3, R304.3.2

N/A Landing X Slope (%)
N/A Shared Landing?
N/A Gutter Ponding?
N/A Gutter Lip Ht (in)
N/A Painted X Walk1?

Total Cost:









1800.00