

Access Compliance Report Public Rights-of-Way (Curb Ramps)



| | | | • | . , | | | | | Location: | |
|---|---------------|---------------------------|---|---|--|----------|-------|-----------------------------|-----------------------------|------|
| Intersection ID: 11974 | Main Str | Main Street: N_BREVARD_ST | | | Cross Street: E_11TH_ST | | | | | S |
| ADA ID: 87E61C2A4E5D | Ramp Ty | Ramp Type: Perp | | | Initial Pass/Fail: Fail Overall Compliance: No | | | | | 22.5 |
| Codes/Mitigation Info/Possible Solution | | | | Field Measurements/Component Compliance | | | | | | |
| | | Possible Solutions: | | | | | | Data Compliance Description | | Data |
| | 5 1 10 | Remove & Replace Ent | Entire Ramp. | N/A | Ramp Leng | th (in) | 77.0 | No | Ramp Slope (%) | 8.5 |
| | 1 1 miles | Restripe Crosswalk | | No | Ramp Width | h (in) | 40.0 | No | Ramp XSlope (%) | 5.0 |
| | | • | | N/A | Flare Type | LT | N/A | N/A | Flare Type RT | N/A |
| B.R. | 1 . Torne | | | N/A | Flare Slope | e LT (%) | N/A | N/A | Flare Slope RT (%) | N/A |
| | | | N/A | Flare Trave | rsable LT? | N/A | N/A | Flare Traversable RT? | N/A | |
| | | | N/A | Landing Ler | ngth (in) | N/A | N/A | DWS Provided? | N/A | |
| | BROOKSHIRE FR | Surveyor Notes: | | N/A | Landing Wie | dth (in) | N/A | N/A | DWS Contrast? | N/A |
| E C | 6. | N/A | | N/A | Landing Slo | ope (%) | N/A | N/A | DWS Length (in) | N/A |
| | | | | N/A | - | | N/A | N/A | DWS Full Width? | N/A |
| | . <u>6</u> | | | N/A | - | | N/A | N/A | DWS Offset (in) | N/A |
| | and the | | | N/A | Shared Lan | ding? | N/A | | | |
| 2 | 1 14 | PROW/ADA: | | N/A | | • | N/A | N/A | Gutter Slope (%) | N/A |
| Not Found, R304.5.1, R304.2.2, | | | N/A | | - | 1.0 | N/A | Gutter X Slope (%) | N/A | |
| 1 an | an ans | R304.5.3 | ,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,, | N/A | Painted X V | Valk1? | Yes | N/A | Painted X Walk2? | N/A |
| | Str. Str. | | | | X Walk 1 Di | rection | To NW | | X Walk 2 Direction | N/A |
| | | | N/A | X Walk 1 W | 'idth (in) | 110.0 | N/A | X Walk 2 Width (in) | N/A | |
| Street 1 Name | N BREVARD ST | | | | X Walk 1 Sl | () | 3.1 | | X Walk 2 Slope (%) | N/A |
| Stop Condition-Street 2 | Signal | | | | X Walk 1 X | , | 3.5 | | X Walk 2 X Slope (%) | N/A |
| Street 2 Name | N/A | | | N/A | | | No | N/A | Ramp inside XWalk2? | N/A |
| Stop Condition-Street 1 | N/A | | | | Road Slope | | N/A | N/A | Clear Space? | N/A |
| · | | | | | Road X Slo | () | N/A | N/A | Clear Space to XWalk (in) | N/A |
| | | | | N/A | | , | N/A | N/A | Storm Grate/Utility Hazard? | N/A |
| | | Total Cost: | \$ 20 | 050.00 | Obstruction | | | | Storm Grate/Utility Type | |
| | | | · | | | | N/A | | , ,, | N/A |
| | | | | | | | • | | | |

Yes Surface Condition? (G/P)

Good

