

ADA ID: 87EBCB54E206

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

5.5

4.8

N/A

Good

Severity Score:

X Walk 2 X Slope (%)

Ramp inside XWalk2?

Clear Space to XWalk (in)

Storm Grate/Utility Type

Surface Condition? (G/P)

Storm Grate/Utility Hazard?

Flare Traversable RT?

Cross Street: SANDERS AV Location: Intersection ID: 9358 Main Street: BEATTIES FORD RD Ν Ramp Type: Perp Initial Pass/Fail: Fail **Overall Compliance: No** 1.25

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

N/A

Yes



SANDERS AV Street 1 Name Stop Condition-Street 2 StopSign Street 2 Name N/A Stop Condition-Street 1 N/A

Possible Solutions:	Comp	pliance Description	Data	Compl	iance	Description
Remove & Replace Entire Ramp.	N/A	Ramp Length (in)	62.0	Yes	Ramp	Slope (%)
	Yes	Ramp Width (in)	65.0	No		XSlope (%)
	N/A	Flare Type LT	N/A	N/A	Flare	Type RT
	N/A	Flare Slope LT (%)	N/A	N/A	Flare	Slope RT (%)
	N/A	Flare Traversable LT?	N/A	N/A	Flare	Traversable R
	N/A	Landing Length (in)	N/A	N/A	DWS	Provided?
Surveyor Notes:	N/A	Landing Width (in)	N/A	N/A	DWS	Contrast?
N/A	N/A	Landing Slope (%)	N/A	N/A	DWS	Length (in)
	N/A	Landing X Slope (%)	N/A	N/A	DWS	Full Width?
	N/A	Landing Curb? (Y/N)	N/A	N/A	DWS	Offset (in)
	N/A	Shared Landing?	N/A			
PROW/ADA:	N/A	Gutter Ponding?	N/A	N/A	Gutte	r Slope (%)
R304.5.3	N/A	Gutter Lip Ht (in)	N/A	N/A	Gutte	r X Slope (%)
	N/A	Painted X Walk1?	No	N/A	Painte	ed X Walk2?
		X Walk 1 Direction	To S		X Wa	lk 2 Direction
	N/A	X Walk 1 Width (in)	N/A	N/A	X Wa	lk 2 Width (in)
		X Walk 1 Slope (%)	3.3		X Wa	lk 2 Slope (%)
		X Walk 1 X Slope (%)	4.3		X Wa	lk 2 X Slope (%
	N/A	Ramp inside XWalk1?	N/A	N/A	Ramp	inside XWalk2
		Road Slope (%)	N/A	N/A	Clear	Space?
		Road X Slope (%)	N/A	N/A	Clear	Space to XWa
	N/A	Any Obstructions?	N/A	N/A	Storm	Grate/Utility H





Total Cost:



1850.00

Obstruction Type