


Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 4616	Main Street: ROZZELLES_FERRY_RD	Cross Street: MONARCH_DR	Location: S
ADA ID: 87F092C1C245	Ramp Type: Directional1	Initial Pass/Fail: Fail	Overall Compliance: No
Codes/Mitigation Info/Possible Solution		Field Measurements/Component Compliance	
Severity Score: 12.5			



Street 1 NameMONARCH DR

Stop Condition-Street 1StopSign

Street 2 NameN/A

Stop Condition-Street 2N/A

Possible Solutions:

Remove & Replace Entire Ramp.

Surveyor Notes:

N/A

PROW/ADA:

R304.5.3

Total Cost:

\$

1600.00

Compliance		Description	Data	Compliance		Description	Data
N/A		Ramp Length (in)	59.0	N/A		Grade Break?	N/A
Yes		Ramp Width (in)	70.0	N/A		Grade Break Slope (%)	0.0
Yes		Ramp Slope (%)	5.0	N/A		Grade Break XSlope (%)	0.0
No		Ramp XSlope (%)	5.4				
N/A		Flare Type LT	N/A	N/A		Flare Type RT	N/A
N/A		Flare Slope LT (%)	N/A	N/A		Flare Slope RT (%)	0.0
N/A		Flare Traversable LT?	N/A	N/A		Flare Traversable RT?	N/A
N/A		Landing Length (in)	0.0	N/A		DWS Provided?	N/A
N/A		Landing Width (in)	0.0	N/A		DWS Contrast?	N/A
N/A		Landing Slope (%)	0.0	N/A		DWS Length (in)	N/A
N/A		Landing X Slope (%)	0.0	N/A		DWS Full Width?	N/A
N/A		Landing Curb? (Y/N)	N/A	N/A		DWS Offset LT (in)	N/A
N/A		Shared Landing?	N/A	N/A		DWS Offset RT (in)	N/A
N/A		Gutter Ponding?	0.0	N/A		Gutter Slope (%)	N/A
N/A		Gutter Lip Ht (in)	0.0	N/A		Gutter X Slope (%)	N/A
N/A		Painted X Walk1?	No			Road Slope (%)	2.9
		X Walk 1 Direction	To N			Road X Slope (%)	4.1
		X Walk 1 Width (in)	N/A			Clear Space?	N/A
		X Walk 1 Slope (%)	2.9	N/A		Clear Space to XWalk (in)	N/A
		X Walk 1 X Slope (%)	4.1	N/A		Storm Grate/Utility Hazard?	N/A
N/A		Ramp inside XWalk1?	N/A			Storm Grate/Utility Type	
N/A		Any Obstructions?	N/A				N/A
		Obstruction Type		Yes		Surface Condition? (G/P)	Good
			N/A	N/A		Curb Slope (%)	0.1

