

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 13795 Main Street: DENBUR_DR Cross Street: LUSTERLEAF_HOLLY_RD Location: N

ADA ID: 881C3711FB87 Ramp Type: Para Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 26.25

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Street 1 Name

Stop Condition-Street 1

Street 2 Name

N/A

Stop Condition-Street 2

N/A

Total Cost: \$ 1600.00

Compliance Description		Data	Compliance Description		Data
N/A	Ramp Length LT (in)	36.5	N/A	Ramp Length RT (in)	50.5
Yes	Ramp Width LT (in)	59.0	Yes	Ramp Width RT (in)	59.5
Yes	Ramp Slope LT (%)	0.4	No	Ramp Slope RT (%)	12.3
No	Ramp XSlope LT (%)	2.3	No	Ramp XSlope RT (%)	3.6
N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
N/A	Shared Landing?	N/A			
N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
	X Walk 1 Direction	To W		X Walk 2 Direction	N/A
N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
	X Walk 1 Slope (%)	1.2		X Walk 2 Slope (%)	N/A
	X Walk 1 X Slope (%)	3.3		X Walk 2 X Slope (%)	N/A
N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
	Road Slope (%)	N/A	N/A	Clear Space?	N/A
	Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
	Obstruction Type			Storm Grate/Utility Type	
		N/A			N/A
			Yes	Surface Condition? (G/P)	Good
			N/A	Curb Slope (%)	16.6





