## cole

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 10033378	378 Main Street: OLD_CLOSEBURN_CT			Cross Street: N/A				Location:	W
ADA ID: 883BCB270E8D	383BCB270E8D Ramp Type: PerpDiag			Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	21.25
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
		Possible Solutions:		Compliance Description		Data	Data Compliance Description		Data
		Remove & Replace Curb Ramp V Two New Directional Ramps or Equivalent.	amp With	N/A	Ramp Length (in)	48.0	Yes	Ramp Slope (%)	5.2
			•	No	Ramp Width (in)	40.0	No	Ramp XSlope (%)	5.8
				N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
OLD GIOS	The state			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
SEBURN	XL AND			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
Fall	A BEE	Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
the second secon	- N. W.	N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
PROW/ADA: Not Found, R304.5.1, R304.5.3				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
				N/A	Shared Landing?	N/A			
				N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
			.5.3	N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
				N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
					X Walk 1 Direction	To E		X Walk 2 Direction	To N
				N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	OLD CLOSEBURN CT				X Walk 1 Slope (%)	3.3		X Walk 2 Slope (%)	0.2
Stop Condition-Street 2	None				X Walk 1 X Slope (%)	2.4		X Walk 2 X Slope (%)	2.8
Street 2 Name	OLD CLOSEBURN CT			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	None				Road Slope (%)	0.2	N/A	Clear Space?	N/A
					Road X Slope (%)	2.2	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost:	\$ 3200.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A

Yes Surface Condition? (G/P)

Good

