

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 28322 Main Street: ARDREY\_KELL\_RD Cross Street: BEAU\_RILEY\_RD Location: NW

ADA ID: 888271E4DE0E Ramp Type: Perp Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 13.75

**Codes/Mitigation Info/Possible Solution** 

## Field Measurements/Component Compliance



Street 1 Name

Stop Condition-Street 2

StopSign

Street 2 Name

N/A

Stop Condition-Street 1

N/A

Possible Solutions:

Remove & Replace Entire Ramp.

N/
N/
N/
N/
Surveyor Notes:
N/A

N/
N/
PROW/ADA:
R304.2.2, R304.5.3

N/
N/
N/

Total Cost: \$ 1850.00

Compliance Description Data Compliance Description Data No N/A Ramp Length (in) 73.0 Ramp Slope (%) 9.9 No Ramp XSlope (%) Yes Ramp Width (in) 52.0 2.4 N/A N/A Flare Type LT N/A Flare Type RT N/A N/A N/A N/A Flare Slope RT (%) N/A Flare Slope LT (%) N/A Flare Traversable LT? N/A N/A Flare Traversable RT? N/A N/A Landing Length (in) N/A N/A DWS Provided? N/A N/A Landing Width (in) N/A N/A **DWS Contrast?** N/A N/A N/A N/A Landing Slope (%) DWS Length (in) N/A N/A Landing X Slope (%) N/A N/A DWS Full Width? N/A N/A Landing Curb? (Y/N) N/A N/A DWS Offset (in) N/A N/A N/A Shared Landing? N/A **Gutter Ponding?** N/A N/A Gutter Slope (%) N/A N/A Gutter Lip Ht (in) N/A N/A Gutter X Slope (%) N/A N/A Painted X Walk1? Yes N/A Painted X Walk2? N/A X Walk 1 Direction To NE X Walk 2 Direction N/A N/A 108.0 N/A X Walk 2 Width (in) X Walk 1 Width (in) N/A X Walk 1 Slope (%) 4.2 X Walk 2 Slope (%) N/A X Walk 1 X Slope (%) 1.2 X Walk 2 X Slope (%) N/A N/A N/A Ramp inside XWalk2? Ramp inside XWalk1? Yes N/A Road Slope (%) N/A N/A Clear Space? N/A N/A Road X Slope (%) N/A Clear Space to XWalk (in) N/A N/A N/A Any Obstructions? N/A Storm Grate/Utility Hazard? N/A **Obstruction Type** Storm Grate/Utility Type N/A N/A Yes Surface Condition? (G/P) Good





