

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 47468 Main Street: MILLSTREAM_RIDGE_DR Cross Street: ELENDIL_LN Location: NE ADA ID: 889060E1E4EA Ramp Type: Perp Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 58.75 Codes/Mitigation Info/Possible Solution Field Measurements/Compliance: Description Data Compliance Description Data Possible Solutions: Remove & Replace Entire Ramp. N/A Ramp Length (in) 46.0 No Ramp Slope (%) 14.3 No Ramp Width (in) 43.0 No Ramp XSlope (%) 8.1
Codes/Mitigation Info/Possible Solution Field Measurements/Component Compliance Possible Solutions: Compliance Description Data Compliance Description Data N/A Ramp Length (in) 46.0 No Ramp Slope (%) 14.3 No Ramp Width (in) 43.0 No Ramp XSlope (%) 8.1
Possible Solutions: Compliance Description Data Compliance Description Data N/A Ramp Length (in) 46.0 No Ramp Slope (%) 14.3 No Ramp Width (in) 43.0 No Ramp XSlope (%) 8.1
No Ramp Width (in) 43.0 No Ramp XSlope (%) 8.1
No Ramp Width (in) 43.0 No Ramp XSlope (%) 8.1
N/A Flare Type LT N/A N/A Flare Type RT N/A
N/A Flare Slope LT (%) N/A Flare Slope RT (%) N/A
N/A Flare Traversable LT? N/A N/A Flare Traversable RT? N/A
N/A Landing Length (in) N/A DWS Provided? N/A
Surveyor Notes: N/A Landing Width (in) N/A DWS Contrast? N/A
N/A N/A DWS Length (in) N/A
N/A Landing X Slope (%) N/A DWS Full Width? N/A
N/A Landing Curb? (Y/N) N/A DWS Offset (in) N/A
N/A Shared Landing? N/A
b N/A Sutter Ponding? N/A N/A Gutter Slope (%) N/A
R304.5.1, R304.2.2, R304.5.3 N/A Gutter Lip Ht (in) N/A M/A Gutter X Slope (%) N/A
N/A Painted X Walk1? No N/A Painted X Walk2? N/A
X Walk 1 Direction To W X Walk 2 Direction N/A
N/A X Walk 1 Width (in) N/A X Walk 2 Width (in) N/A
Street 1 Name MILLSTREAM RIDGE DR X Walk 1 Slope (%) 1.4 X Walk 2 Slope (%) N/A
Stop Condition-Street 2 None X Walk 1 X Slope (%) 10.1 X Walk 2 X Slope (%) N/A
Street 2 Name N/A N/A Ramp inside XWalk1? N/A N/A Ramp inside XWalk2? N/A
Stop Condition-Street 1 N/A N/A Clear Space? N/A
Road X Slope (%) N/A N/A Clear Space to XWalk (in) N/A
N/A Any Obstructions? N/A N/A Storm Grate/Utility Hazard? N/A
Total Cost: \$ 1850.00 Obstruction Type Storm Grate/Utility Type
N/A N/A

s Surface Condition? (G/P)

Good

