## cole

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



ntersection ID: 12416 Main Street: CHESTNUT_AV		Cross Street: THOMAS_AV					Location:	SE
ADA ID: 88B8399EAA22 Ramp T	AA22 Ramp Type: PerpDiag		ss/Fa	il: Fail Overall C	o Severity Score:	10		
Codes/Mitigation Info/Possible Solution		Field Measurements/Component Compliance						
5 SEESTINUE AV	Possible Solutions:	C	Compliance Description			Data Compliance Description		
	Remove & Replace Curb Ramp W	/ith N	I/A	Ramp Length (in)	75.0	Yes	Ramp Slope (%)	5.4
	Two New Directional Ramps or		lo	Ramp Width (in)	47.0	No	Ramp XSlope (%)	3.5
	Equivalent.	Ν	I/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
		Ν	I/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
		Ν	I/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
			I/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
	Surveyor Notes:	Ν	I/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
	N/A	Ν	I/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
	11/2	Ν	I/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
			I/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
		Ν	I/A	Shared Landing?	N/A			
	PROW/ADA:		I/A	Gutter Ponding?	Yes	N/A	Gutter Slope (%)	N/A
	R304.5.1, R304.5.3	Ν	I/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
	1004.0.1, 1004.0.0		I/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
				X Walk 1 Direction	To N		X Walk 2 Direction	To W
		Ν	I/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name CHESTNUT AV	-			X Walk 1 Slope (%)	3.3		X Walk 2 Slope (%)	3.2
Stop Condition-Street 2 StopSign				X Walk 1 X Slope (%)	1.8		X Walk 2 X Slope (%)	1.6
Street 2 Name THOMAS AV		Ν	I/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1 StopSign				Road Slope (%)	5.4	N/A	Clear Space?	N/A
				Road X Slope (%)	0.1	N/A	Clear Space to XWalk (in)	N/A
		N	N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
	Total Cost: \$ 32	200.00		Obstruction Type			Storm Grate/Utility Type	
					N/A			N/A

Yes Surface Condition? (G/P)

Good

