cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 13437 Ma	Main Street: TRYSTING_RD		Cross Street: WOODWEDGE_DR			Location:	NW	
ADA ID: 8926090F0BE7 Ra	Ramp Type: BlendTrans1		nitial Pass/Fail: Fail Overall Compliance: N			o Severity Score:	8.75	
Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance					
	Possible Solutions:	Comp	Compliance Description Data		Compliance Description		Data	
	Remove & Replace Curb Ramp W	/ith N/A	Ramp Length (in)	37.0	Yes	BlendTrans Slope (%)	2.6	
	Two New Directional Ramps or Equivalent.	No	Ramp Width (in)	47.0	Yes	BlendTrans XSlope (%)	0.8	
		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
		N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
		N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
	and the second se	N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
	Surveyor Notes:	N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
	N/A	N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
		N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
		N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
A CONTRACTOR OF THE OWNER		N/A	Shared Landing?	N/A				
A MARKE MARK	PROW/ADA:	N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
The second second	Not Found, R304.5.1	N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
		N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A	
15 15 1 1 1 1 1 1 1	ANT IN COLUMN		X Walk 1 Direction	To SE		X Walk 2 Direction	N/A	
S S STATE TO STATE	the second se		X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A	
Street 1 Name WOODWEDG	E DR		X Walk 1 Slope (%)	1.7		X Walk 2 Slope (%)	N/A	
Stop Condition-Street 1 Stop	Sign		X Walk 1 X Slope (%)	1.0		X Walk 2 X Slope (%)	N/A	
Street 2 Name	N/A	N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
Stop Condition-Street 2	N/A		Road Slope (%)	1.0		Clear Space?	N/A	
			Road X Slope (%)	1.7	N/A	Clear Space to XWalk (in)	N/A	
		N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A	
	Total Cost: \$ 32	00.00	Obstruction Type			Storm Grate/Utility Type		
				N/A			N/A	







Yes

No

Surface Condition? (G/P)

Curb Slope (%)

Good

26.2