

## **Access Compliance Report Public Rights-of-Way** (Curb Ramps)



Data

58.0

58.0

5.2

2.2

6.8

1.4

10.5

No

Yes

Yes

24.4

Yes

4.0

Sloped

Main Street: N TRYON ST Cross Street: N/A Location: S Intersection ID: 10016647

Initial Pass/Fail: Pass **Overall Compliance: No** 0.25 ADA ID: 895A5B03D21A Ramp Type: Combination1 **Severity Score:** 

## Codes/Mitigation Info/Possible Solution

## **Field Measurements/Component Compliance**

N/A

Yes

Yes

No

Yes

Yes

N/A

N/A

N/A

Yes

Yes

1.4 Yes

1.4 Yes

Compliance Description

Ramp Length RT (in)

Ramp Width RT (in)

Ramp Slope RT (%)

Ramp Slope (%)

Ramp XSlope (%)

Flare Slope RT (%)

DWS Provided?

**DWS Contrast?** 

DWS Length (in)

DWS Full Width?

Curb Slope (%)

Flare Traversable RT?

Flare Type RT

Ramp XSlope RT (%)

Data

119.0

56.0

7.9

1.9

44.0

60.0

22.0

No

57.5

60.0

Sloped

Flare Traversable LT?

Ramp XSlope LT (%)



Street 1 Name Signal N TRYON ST Stop Condition-Street 1 Street 2 Name N/A Stop Condition-Street 2 N/A

Possible Solution		Field Me	
Possible Solutions:	Comp	liance Description	
Remove & Replace Entire Ramp.	N/A	Ramp Length LT (in)	
·	Yes	Ramp Width LT (in)	
	Yes	Ramp Slope LT (%)	
	Yes	Ramp XSlope LT (%	
	N/A	Ramp Length (in)	
	Yes	Ramp Width (in)	
Surveyor Notes:	N/A	Flare Type LT	
SIGNAL UNDER CONSTRUCTION	N/A	Flare Slope LT (%)	
	N/A	Flare Traversable LT	
	No	Landing Length (in)	
	Yes	Landing Width (in)	
PROW/ADA:	Yes	Landing Slope (%)	
R304.5.3, R304.2.1	Yes	Landing X Slope (%)	
	N/A	Landing Curb? (Y/N	
	N/A	Shared Landing?	
	Yes	Gutter Ponding?	
	Yes	Gutter Lip Ht (in)	
	N/A	Painted X Walk1?	
		X Walk 1 Direction	
		X Walk 1 Width (in)	
		X Walk 1 Slope (%)	





Total Cost:



1800.00

N/A	Landing Curb? (Y/N)	Yes	Yes	DWS Offset (in)	0.0
N/A	Shared Landing?	Yes			
Yes	Gutter Ponding?	No	Yes	Gutter Slope (%)	3.9
Yes	Gutter Lip Ht (in)	0.0	Yes	Gutter X Slope (%)	1.6
N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
	X Walk 1 Direction	To N		X Walk 2 Direction	N/A
	X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
	X Walk 1 Slope (%)	3.7		X Walk 2 Slope (%)	N/A
	X Walk 1 X Slope (%)	2.2		X Walk 2 X Slope (%)	N/A
N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
	Road Slope (%)	N/A		Clear Space?	Yes
	Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
24.62	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		Yes	Any Obstruction?	No
	A Company of the Comp			Obstruction Type	
					N/A
-5			Yes	Storm Grate/Utility Hazard?	No
				Storm Grate/Utility Type	
de la					N/A
-			Yes	Surface Condition? (G/P)	Good