

Access Compliance Report Public Rights-of-Way (Curb Ramps)



		•		- /					
Intersection ID: 28255	Main Street: REA_RD			Cross Street: ARDREY_KELL_RD				Location:	NE
ADA ID: 896C01B39775	9775 Ramp Type: Perp			Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	17.5
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
		Possible Solutions:		Compliance Description			Data Compliance Description		
		Remove & Replace Entire Ra	amp.	N/A	Ramp Length (in)	136.0	Yes	Ramp Slope (%)	6.9
	Cal N P			No	Ramp Width (in)	32.0	Yes	Ramp XSlope (%)	0.9
	P. Mater			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
CD La I PA	XXX			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
	and a second			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
C AREL I VICE				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
	and the set	Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
Summer marks	COLOR D.	N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
Land Barrie Constant				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
	A CONTRACTOR OF A CONTRACTOR OFTA CONT			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
				N/A	Shared Landing?	N/A			
	·····	PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
Not Found, R304.5.1				N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
the second secon	and the second second	,		N/A	Painted X Walk1?	Yes	N/A	Painted X Walk2?	N/A
TOTAL DITTUTE & C.	Statute and statute of the				X Walk 1 Direction	To W		X Walk 2 Direction	N/A
half. Par	- 6. P			N/A	X Walk 1 Width (in)	112.0	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	REA RD	-			X Walk 1 Slope (%)	4.0		X Walk 2 Slope (%)	N/A
Stop Condition-Street 2	Signal				X Walk 1 X Slope (%)	1.1		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A			N/A	Ramp inside XWalk1?	Yes	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	N/A				Road Slope (%)	N/A	N/A	Clear Space?	N/A
					Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$	1850.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A

Yes Surface Condition? (G/P)

Good

