

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

9.5

34.5

11.7

1.5

7.9

1.3

N/A

Intersection ID: 9246 Main Street: GRIMES ST **Cross Street: NORRIS AV** W Location: **Overall Compliance: No Severity Score:** 30 ADA ID: 89AA4087647B Ramp Type: Combination1 Initial Pass/Fail: Fail

Compliance Description

N/A

No

Yes

Yes

N/A

No

N/A

Ramp Length LT (in)

Ramp Width LT (in)

Ramp Slope LT (%)

Ramp Length (in)

Ramp Width (in)

Flare Slope LT (%)

Landing Length (in)

Landing Width (in)

Landing Slope (%)

Landing X Slope (%)

Landing Curb? (Y/N)

Shared Landing?

Gutter Ponding?

Gutter Lip Ht (in)

Painted X Walk1?

X Walk 1 Direction

X Walk 1 Width (in)

X Walk 1 Slope (%)

X Walk 1 X Slope (%)

Flare Traversable LT?

Flare Type LT

Ramp XSlope LT (%)

Codes/Mitigation Info/Possible Solution

Total Cost:

Field Measurements/Component Compliance

N/A

No

No

Yes

Yes

Yes

N/A

Compliance Description

Ramp Length RT (in)

Ramp Width RT (in)

Ramp Slope RT (%)

Ramp XSlope RT (%)

Ramp Slope (%)

Flare Type RT

Ramp XSlope (%)

Flare Slope RT (%)

DWS Provided?

DWS Contrast?

DWS Length (in)

DWS Full Width?

DWS Offset (in)

Gutter Slope (%)

Gutter X Slope (%)

Painted X Walk2?

X Walk 2 Direction

X Walk 2 Width (in)

X Walk 2 Slope (%)

X Walk 2 X Slope (%)

Flare Traversable RT?

Data

N/A

38.0

0.9

1.1

29.0

47.5

N/A

No

N/A

0.9

4.2

To NE



Street 1 Name StopSign **GRIMES ST** Stop Condition-Street 1 N/A Street 2 Name Stop Condition-Street 2 N/A Possible Solutions: Remove & Replace Entire Ramp. Surveyor Notes: LT RP < 5% PROW/ADA: Not Found, R304.5.1, R304.5.1, R304.3.2





1800.00 N/A Ramp inside XWalk1? N/A N/A Ramp inside XWalk2? N/A Road Slope (%) N/A Clear Space? N/A Road X Slope (%) N/A N/A Clear Space to XWalk (in) N/A N/A Any Obstruction? N/A **Obstruction Type** N/A N/A Storm Grate/Utility Hazard? N/A Storm Grate/Utility Type N/A Yes Surface Condition? (G/P) Good 13.2 Curb Slope (%)