

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 10033355 Main Street: OLD_ARDREY_KELL_RD Cross Street: N/A Location: NE **Overall Compliance: No** ADA ID: 89B09BDDEB8C Ramp Type: Perp Initial Pass/Fail: Fail **Severity Score:** 12.5

Codes/Mitigation Info/Possible Solution



ENTRANCE Street 1 Name Stop Condition-Street 2 StopSign Street 2 Name N/A Stop Condition-Street 1 N/A

Possible Solutions:	Cor
Remove & Replace Entire Ramp.	N/A
•	Yes
	N/A
	N/A
	N/A
	N/A
Surveyor Notes:	N/A
N/A	N/A
	N/A
	N/A
	N/A
PROW/ADA:	N/A
Not Found, R304.2.2	N/A
	N/A
	N/A
	N/A

Total Cost: 1850.00

Field Measurements/Component Compliance								
Compliance Description		Data	Comp	liance	Description	Data		
N/A	Ramp Length (in)	87.0	No	Ramp	Slope (%)	8.5		
Yes	Ramp Width (in)	48.0	Yes	Ramp	XSlope (%)	1.9		
N/A	Flare Type LT	N/A	N/A	Flare	Type RT	N/A		
N/A	Flare Slope LT (%)	N/A	N/A	Flare	Slope RT (%)	N/A		
N/A	Flare Traversable LT?	N/A	N/A	Flare	Traversable RT?	N/A		
N/A	Landing Length (in)	N/A	N/A	DWS	Provided?	N/A		
N/A	Landing Width (in)	N/A	N/A	DWS	Contrast?	N/A		
N/A	Landing Slope (%)	N/A	N/A	DWS	Length (in)	N/A		
N/A	Landing X Slope (%)	N/A	N/A	DWS	Full Width?	N/A		
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS	Offset (in)	N/A		
N/A	Shared Landing?	N/A						
N/A	Gutter Ponding?	N/A	N/A	Gutter	Slope (%)	N/A		
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter	X Slope (%)	N/A		
N/A	Painted X Walk1?	No	N/A	Painte	ed X Walk2?	N/A		
	X Walk 1 Direction	To S		X Wal	k 2 Direction	N/A		
N/A	X Walk 1 Width (in)	N/A	N/A	X Wal	k 2 Width (in)	N/A		
	X Walk 1 Slope (%)	2.7		X Wal	k 2 Slope (%)	N/A		
	X Walk 1 X Slope (%)	1.2		X Wal	k 2 X Slope (%)	N/A		
N/A	Ramp inside XWalk1?	N/A	N/A	Ramp	inside XWalk2?	N/A		
	Road Slope (%)	N/A	N/A	Clear	Space?	N/A		
	Road X Slope (%)	N/A	N/A	Clear	Space to XWalk (in)	N/A		
N/A	Any Obstructions?	N/A	N/A	Storm	Grate/Utility Hazard?	N/A		
	Obstruction Type			Storm	Grate/Utility Type			
		N/A				N/A		
			Yes	Surfac	ce Condition? (G/P)	Good		





