## cole

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



		•		-					
Intersection ID: 23300	Main Street: SHARON_RD_WEST			Street:	SHARONBROOK_DR	Location:	NE		
ADA ID: 89FAD0F852BF	2BF Ramp Type: PerpDiag			Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	13.75
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
		Possible Solutions:		Compliance Description			Data Compliance Description		
		Remove & Replace Curb Ramp	With	N/A	Ramp Length (in)	59.0	No	Ramp Slope (%)	9.0
		Two New Directional Ramps or		Yes	Ramp Width (in)	48.0	No	Ramp XSlope (%)	2.8
		Equivalent.		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
The Contraction				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
		N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
SHAROM				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
CS CS	D WEAR			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5	10 Ka			N/A	Shared Landing?	N/A			
		PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
	Part and a state of the state o	R304.2.2, R304.5.3		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
	A CONTRACTOR	1004.2.2, 1004.0.0		N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
PROW/ADA: R304.2.2, R304.5.3					X Walk 1 Direction	To S		X Walk 2 Direction	To SE
	Contraction dates			N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	SHARON RD WEST	-			X Walk 1 Slope (%)	4.2		X Walk 2 Slope (%)	3.2
Stop Condition-Street 2	None				X Walk 1 X Slope (%)	0.9		X Walk 2 X Slope (%)	4.2
Street 2 Name	SHARONBROOK DR			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	StopSign				Road Slope (%)	3.5		Clear Space?	N/A
					Road X Slope (%)	2.1	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?		N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$	3200.00		Obstruction Type	1003		Storm Grate/Utility Type	
		····· ••••				N/A			N/A
						104			

Yes Surface Condition? (G/P)

Good

