


Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

| | | | |
|---|---------------------------------|---|------------------------|
| Intersection ID: 10034961 | Main Street: PROVIDENCE_RD_WEST | Cross Street: N/A | Location: SW |
| ADA ID: 8A54203E2761 | Ramp Type: PerpDiag | Initial Pass/Fail: Fail | Overall Compliance: No |
| Codes/Mitigation Info/Possible Solution | | Field Measurements/Component Compliance | |

| | | | | | | |
|--|-------------------------|--|---|--|--|--|
|  | Possible Solutions: | | Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent. | | | |
| | Surveyor Notes: | | N/A | | | |
| | PROW/ADA: | | R304.5.1, R304.2.2 | | | |
| | Street 1 Name | | ENTRANCE | | | |
| | Stop Condition-Street 2 | | StopSign | | | |
| | Street 2 Name | | PROVIDENCE RD WEST | | | |
| | Stop Condition-Street 1 | | None | | | |
| | Total Cost: | | \$ 3200.00 | | | |
| | | | | | | |
| | | | | | | |

| Compliance | Description | Data | Compliance | Description | Data |
|------------|-----------------------|-------|------------|-----------------------------|------|
| N/A | Ramp Length (in) | 53.0 | No | Ramp Slope (%) | 9.7 |
| No | Ramp Width (in) | 47.0 | Yes | Ramp XSlope (%) | 0.1 |
| N/A | Flare Type LT | N/A | N/A | Flare Type RT | N/A |
| N/A | Flare Slope LT (%) | N/A | N/A | Flare Slope RT (%) | N/A |
| N/A | Flare Traversable LT? | N/A | N/A | Flare Traversable RT? | N/A |
| N/A | Landing Length (in) | N/A | N/A | DWS Provided? | N/A |
| N/A | Landing Width (in) | N/A | N/A | DWS Contrast? | N/A |
| N/A | Landing Slope (%) | N/A | N/A | DWS Length (in) | N/A |
| N/A | Landing X Slope (%) | N/A | N/A | DWS Full Width? | N/A |
| N/A | Landing Curb? (Y/N) | N/A | N/A | DWS Offset (in) | N/A |
| N/A | Shared Landing? | N/A | | | |
| N/A | Gutter Ponding? | N/A | N/A | Gutter Slope (%) | N/A |
| N/A | Gutter Lip Ht (in) | N/A | N/A | Gutter X Slope (%) | N/A |
| N/A | Painted X Walk1? | No | N/A | Painted X Walk2? | No |
| | X Walk 1 Direction | To NE | | X Walk 2 Direction | To N |
| N/A | X Walk 1 Width (in) | N/A | N/A | X Walk 2 Width (in) | N/A |
| | X Walk 1 Slope (%) | 5.3 | | X Walk 2 Slope (%) | 2.8 |
| | X Walk 1 X Slope (%) | 3.4 | | X Walk 2 X Slope (%) | 4.1 |
| N/A | Ramp inside XWalk1? | N/A | N/A | Ramp inside XWalk2? | N/A |
| | Road Slope (%) | 0.5 | N/A | Clear Space? | N/A |
| | Road X Slope (%) | 6.1 | N/A | Clear Space to XWalk (in) | N/A |
| N/A | Any Obstructions? | N/A | N/A | Storm Grate/Utility Hazard? | N/A |
| | Obstruction Type | | | Storm Grate/Utility Type | |
| | | N/A | | | N/A |
| | | | Yes | Surface Condition? (G/P) | Good |

