

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Interrection ID: 8067	terestian ID: 9067 Main Street: BRADEORD DD				Cross Street: LYNN_ST				C/M
Intersection ID: 8967	7 Main Street: BRADFORD_DR			Street:	LTNN_51			Location:	SW
ADA ID: 8A956AD53F95 Ramp Type: Perp			Initial	Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	27.5
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
	1 and 1 and	Possible Solutions:		Compliance Description			Data Compliance Description		Data
		Remove & Replace Entire Ran	ıp.	N/A	Ramp Length (in)	53.0	No	Ramp Slope (%)	9.0
	and the second		•	Yes	Ramp Width (in)	48.0	Yes	Ramp XSlope (%)	1.1
- She shall be and the state				N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
	A CAS			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
H L	TELMINY			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
ting the second s	THE REAL PROPERTY.	Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
	1 448	N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
	1			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
				N/A	Shared Landing?	N/A			
	11. 2.	PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
	A L	Not Found, R304.2.2, R302.7		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
	1	,,,,		N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
	w.70				X Walk 1 Direction	To E		X Walk 2 Direction	N/A
				N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	BRADFORD DR	-			X Walk 1 Slope (%)	3.1		X Walk 2 Slope (%)	N/A
Stop Condition-Street 2	None				X Walk 1 X Slope (%)	1.0		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	N/A				Road Slope (%)	N/A	N/A	Clear Space?	N/A
					Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$	1850.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A

No Surface Condition? (G/P)

Poor

