

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 19435	Main Street: MANNING_DR			Cross Street: WINTERCREST_LN				Location: E		
ADA ID: 8A9621B1E4CF	Ramp Type: Directional1			Initial Pass/Fail: Fail Overall Compliance			nce: N	o Severity Score:	12.5	
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance						
	10.10	Possible Solutions:		Compliance Description Data C			Comp	Compliance Description Data		
and the server the		Remove & Replace Entire Ramp		N/A	Ramp Length (in)	127.0	N/A	Grade Break?	N/A	
	144			Yes	Ramp Width (in)	61.0	N/A	Grade Break Slope (%)	0.0	
STATES A TATES	Eler VIII			No	Ramp Slope (%)	9.3	N/A	Grade Break XSlope (%)	0.0	
VIII AND I AND	110			Yes	Ramp XSlope (%)	1.8				
				N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
Million Million	71 200 - 2			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	0.0	
	ROREST_LN	Surveyor Notes:		N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
	20	N/A		N/A	Landing Length (in)	0.0	N/A	DWS Provided?	N/A	
	Mar Carlo			N/A	Landing Width (in)	0.0	N/A	DWS Contrast?	N/A	
				N/A	Landing Slope (%)	0.0	N/A	DWS Length (in)	N/A	
			N/A	Landing X Slope (%)	0.0	N/A	DWS Full Width?	N/A		
A HANNER	the and that	PROW/ADA:		N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset LT (in)	N/A	
	and I'l SI	R304.2.2		N/A	Shared Landing?	N/A	N/A	DWS Offset RT (in)	N/A	
	and the			N/A	Gutter Ponding?	0.0	N/A	Gutter Slope (%)	N/A	
				N/A	Gutter Lip Ht (in)	0.0	N/A	Gutter X Slope (%)	N/A	
A SA			N/A	Painted X Walk1?	No		Road Slope (%)	1.0		
Street 1 Name	MANNING DR	-			X Walk 1 Direction	To W		Road X Slope (%)	2.7	
Stop Condition-Street 1	StopSign				X Walk 1 Width (in)	N/A		Clear Space?	N/A	
Street 2 Name	N/A				X Walk 1 Slope (%)	1.0	N/A	Clear Space to XWalk (in)	N/A	
Stop Condition-Street 2	N/A				X Walk 1 X Slope (%)	2.7	N/A	Storm Grate/Utility Hazard?	N/A	
				N/A	Ramp inside XWalk1?	N/A		Storm Grate/Utility Type		
				N/A	Any Obstructions?	N/A			N/A	
		Total Cost: \$	1600.00		Obstruction Type		Yes	Surface Condition? (G/P)	Good	
						N/A	N/A	Curb Slope (%)	8.9	

