

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

Intersection ID: 5672 Main Street: SUNSET\_RD Cross Street: BEATTIES\_FORD\_RD Location: SE

ADA ID: 8AC976385F72 Ramp Type: Perp Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 21.25

Codes/Mitigation Info/Possible Solution

## Field Measurements/Component Compliance

Data Compliance Description



Street 1 Name

Stop Condition-Street 2

Signal
Street 2 Name

N/A

Stop Condition-Street 1

N/A

Possible Solutions:

Remove & Replace Entire Ramp.

N/A Ramp Length (in)
No Ramp Width (in)
N/A Flare Type LT
N/A Flare Slope LT (%)
N/A Landing Length (in)
N/A Landing Length (in)
N/A Landing Slope (%)
N/A Landing Slope (%)
N/A Landing Slope (%)
N/A Landing Curb? (Y/N
N/A Shared Landing?
PROW/ADA:

Not Found, R304.5.1, R304.2.2

N/A Gutter Ponding?
N/A Gutter Lip Ht (in)
N/A Painted X Walk1?
X Walk 1 Direction
N/A X Walk 1 Width (in)

PROW/ADA: N/A
Not Found, R304.5.1, R304.2.2 N/A
N/A
N/A
N/A

N/A

Total Cost: \$ 1850.00

N/A	Ramp Length (in)	60.0	No	Ramp Slope (%)	8.5
No	Ramp Width (in)	47.0	Yes	Ramp XSlope (%)	1.7
N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
N/A	Shared Landing?	N/A			
N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
N/A	Painted X Walk1?	Yes	N/A	Painted X Walk2?	N/A
	X Walk 1 Direction	To W		X Walk 2 Direction	N/A
N/A	X Walk 1 Width (in)	92.0	N/A	X Walk 2 Width (in)	N/A
	X Walk 1 Slope (%)	3.3		X Walk 2 Slope (%)	N/A
	X Walk 1 X Slope (%)	1.8		X Walk 2 X Slope (%)	N/A
N/A	Ramp inside XWalk1?	Yes	N/A	Ramp inside XWalk2?	N/A
	Road Slope (%)	N/A	N/A	Clear Space?	N/A
	Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
	Obstruction Type			Storm Grate/Utility Type	
		N/A			N/A
			Yes	Surface Condition? (G/P)	Good





