


## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: N/AMain Street: E\_4TH\_STCross Street: N/ALocation:SADA ID: 8B155904E36ERamp Type: PerpInitial Pass/Fail: FailOverall Compliance: NoSeverity Score: 13.75

Codes/Mitigation Info/Possible Solution

## Field Measurements/Component Compliance



Street 1 Name E 4TH ST
Stop Condition-Street 2 Signal
Street 2 Name N/A
Stop Condition-Street 1 N/A

Total Cost: \$ 1850.00

Field Measurements/Component Compliance						
Comp	liance Description	Data	Comp	liance	Description	Data
N/A	Ramp Length (in)	76.0	No	Ram	Slope (%)	8.9
Yes	Ramp Width (in)	53.0	Yes	Ram	XSlope (%)	2.4
N/A	Flare Type LT	N/A	N/A	Flare	Type RT	N/A
N/A	Flare Slope LT (%)	N/A	N/A	Flare	Slope RT (%)	N/A
N/A	Flare Traversable LT?	No	N/A	Flare	Traversable RT?	No
N/A	Landing Length (in)	N/A	N/A	DWS	Provided?	N/A
N/A	Landing Width (in)	N/A	N/A	DWS	Contrast?	N/A
N/A	Landing Slope (%)	N/A	N/A	DWS	Length (in)	N/A
N/A	Landing X Slope (%)	N/A	N/A	DWS	Full Width?	N/A
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS	Offset (in)	N/A
N/A	Shared Landing?	N/A				
N/A	Gutter Ponding?	N/A	N/A	Gutte	er Slope (%)	N/A
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutte	er X Slope (%)	N/A
N/A	Painted X Walk1?	Yes	N/A	Paint	ed X Walk2?	N/A
	X Walk 1 Direction	To NE		X Wa	lk 2 Direction	N/A
N/A	X Walk 1 Width (in)	32.0	N/A	X Wa	lk 2 Width (in)	N/A
	X Walk 1 Slope (%)	6.5		X Wa	lk 2 Slope (%)	N/A
	X Walk 1 X Slope (%)	4.4		X Wa	lk 2 X Slope (%)	N/A
N/A	Ramp inside XWalk1?	Yes	N/A	Ram	o inside XWalk2?	N/A
	Road Slope (%)	N/A	N/A	Clear	Space?	N/A
	Road X Slope (%)	N/A	N/A	Clear	Space to XWalk (in)	N/A
N/A	Any Obstructions?	N/A	N/A	Storn	n Grate/Utility Hazard?	N/A
	Obstruction Type			Storn	n Grate/Utility Type	
		N/A				N/A
			Yes	Surfa	ce Condition? (G/P)	Good





