

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 19908Main Street:BROWN-GRIER_RDCross Street:GALLANT_LNLocation:NWADA ID: 8B3339D0CAD0Ramp Type:Directional1Initial Pass/Fail:FailOverall Compliance:NoSeverity Score:12.5

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Street 1 Name	BROWN-GRIER RD
Stop Condition-Street 1	Signal
Street 2 Name	N/A
Stop Condition-Street 2	N/A

Possible Solutions:

Remove & Replace Entire Ramp.

Surveyor Notes:
N/A

PROW/ADA:
R304.5.3

Total Cost:	\$ 1600.00

Field Measurements/Component Compliance									
	Compli	ance Description	Data	Compli	ance	Description	Data		
	N/A	Ramp Length (in)	33.0	N/A	Grad	e Break?	N/A		
	Yes	Ramp Width (in)	71.5	N/A	Grad	e Break Slope (%)	0.0		
	Yes	Ramp Slope (%)	1.4	N/A	Grad	e Break XSlope (%)	0.0		
	No	Ramp XSlope (%)	5.2						
	N/A	Flare Type LT	N/A	N/A	Flare	Type RT	N/A		
	N/A	Flare Slope LT (%)	N/A	N/A	Flare	Slope RT (%)	0.0		
	N/A	Flare Traversable LT?	N/A	N/A	Flare	Traversable RT?	N/A		
	N/A	Landing Length (in)	0.0	N/A	DWS	Provided?	N/A		
	N/A	Landing Width (in)	0.0	N/A	DWS	Contrast?	N/A		
	N/A	Landing Slope (%)	0.0	N/A	DWS	Length (in)	N/A		
	N/A	Landing X Slope (%)	0.0	N/A	DWS	Full Width?	N/A		
	N/A	Landing Curb? (Y/N)	N/A	N/A	DWS	Offset LT (in)	N/A		
	N/A	Shared Landing?	N/A	N/A	DWS	Offset RT (in)	N/A		
	N/A	Gutter Ponding?	0.0	N/A	Gutte	er Slope (%)	N/A		
	N/A	Gutter Lip Ht (in)	0.0	N/A	Gutte	er X Slope (%)	N/A		
	N/A	Painted X Walk1?	Yes		Road	Slope (%)	4.9		
		X Walk 1 Direction	To S		Road	X Slope (%)	5.3		
		X Walk 1 Width (in)	110.0		Clear	Space?	N/A		
		X Walk 1 Slope (%)	4.9	N/A	Clear	Space to XWalk (in)	N/A		
		X Walk 1 X Slope (%)	5.3	N/A	Storn	n Grate/Utility Hazard?	N/A		
	N/A	Ramp inside XWalk1?	Yes		Storn	n Grate/Utility Type			
	N/A	Any Obstructions?	N/A				N/A		
		Obstruction Type		Yes	Surfa	ice Condition? (G/P)	Good		
			N/A	N/A	Curb	Slope (%)	4.8		





