

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 10637	Main St	reet: COKER_AV	Cross	Cross Street: MATHIS_DR				Location:	Ν
ADA ID: 8B4686FAE9B3	Ramp Type: BlendTrans2			Initial Pass/Fail: Fail Overall Compliance: No				Severity Score:	1.25
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
		Possible Solutions:		Compliance Description Data Con			Comp	mpliance Description Data	
		Remove & Replace Curb Ramp V	Nith	N/A	Ramp Length (in)	159.0	Yes	BlendTrans Slope (%)	2.5
		Two New Directional Ramps or		Yes	Ramp Width (in)	60.0	No	BlendTrans XSlope (%)	2.1
		Equivalent.		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
		N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
and the second s		Va		N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
6	Star A			N/A	Shared Landing?	N/A			
		PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
		Not Found, R304.5.3		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
				N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
					X Walk 1 Direction	To SE		X Walk 2 Direction	N/A
		÷			X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
Street 1 Name	COKER AV	-			X Walk 1 Slope (%)	3.1		X Walk 2 Slope (%)	N/A
Stop Condition-Street 1	StopSign				X Walk 1 X Slope (%)	2.0		X Walk 2 X Slope (%)	N/A
Street 2 Name	. c N/A			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 2	N/A				Road Slope (%)	2.0		Clear Space?	N/A
					Road X Slope (%)	3.1	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$ 32	200.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A





Yes

No

Surface Condition? (G/P)

Curb Slope (%)

Good

8.9