


# Access Compliance Report

## Public Rights-of-Way

### (Curb Ramps)

Intersection ID: N/A	Main Street: NATIONS_FORD_RD	Cross Street: IVERIFY	Location: NE
ADA ID: 8B97A75FF9A1	Ramp Type: ParaDiag	Initial Pass/Fail: Fail	Overall Compliance: No
Codes/Mitigation Info/Possible Solution		Field Measurements/Component Compliance	

	Possible Solutions:		Compliance		Description		Data	Compliance	Description	Data
	Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.		N/A		Ramp Length LT (in)		51.0	N/A	Ramp Length RT (in)	61.0
<p>Surveyor Notes:</p> <p>RT RP &lt; 5%</p>			Yes		Ramp Width LT (in)		75.0	Yes	Ramp Width RT (in)	65.0
			No		Ramp Slope LT (%)		12.9	Yes	Ramp Slope RT (%)	2.6
<p>PROW/ADA:</p> <p>R304.3.2, R304.5.3</p>			No		Ramp XSlope LT (%)		2.3	No	Ramp XSlope RT (%)	4.5
			N/A		Landing Length (in)		N/A	N/A	DWS Provided?	N/A
			N/A		Landing Width (in)		N/A	N/A	DWS Contrast?	N/A
			N/A		Landing Slope (%)		N/A	N/A	DWS Length (in)	N/A
			N/A		Landing X Slope (%)		N/A	N/A	DWS Full Width?	N/A
			N/A		Landing Curb? (Y/N)		N/A	N/A	DWS Offset (in)	N/A
			N/A		Shared Landing?		N/A			
			N/A		Gutter Ponding?		N/A	N/A	Gutter Slope (%)	N/A
			N/A		Gutter Lip Ht (in)		N/A	N/A	Gutter X Slope (%)	N/A
			N/A		Painted X Walk1?		No	N/A	Painted X Walk2?	No
					X Walk 1 Direction		To W		X Walk 2 Direction	To S
			N/A		X Walk 1 Width (in)		N/A	N/A	X Walk 2 Width (in)	N/A
					X Walk 1 Slope (%)		2.3		X Walk 2 Slope (%)	1.9
					X Walk 1 X Slope (%)		0.2		X Walk 2 X Slope (%)	4.0
			N/A		Ramp inside XWalk1?		N/A	N/A	Ramp inside XWalk2?	N/A
					Road Slope (%)		0.0	N/A	Clear Space?	N/A
					Road X Slope (%)		4.3	N/A	Clear Space to XWalk (in)	N/A
			N/A		Any Obstructions?		N/A	N/A	Storm Grate/Utility Hazard?	N/A
					Obstruction Type				Storm Grate/Utility Type	
							N/A			N/A
								Yes	Surface Condition? (G/P)	Good
								N/A	Curb Slope (%)	7.6

Total Cost: \$ 3200.00

