


# Access Compliance Report

## Public Rights-of-Way

### (Curb Ramps)

Intersection ID: 10006798	Main Street: HOLBROOK_DR	Cross Street: N SHARON AMITY RD	Location:	NW
ADA ID: 8C9BFE0BB452	Ramp Type: Perp	Initial Pass/Fail: Fail	Overall Compliance: No	Severity Score: 1.25

Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance		
	Possible Solutions:		<b>Compliance</b>	<b>Description</b>	<b>Data</b>
	<b>Remove &amp; Replace Entire Ramp.</b>		<b>Yes</b>	Ramp Length (in)	25.0
			<b>N/A</b>	Ramp Width (in)	59.5
			<b>N/A</b>	Flare Type LT	N/A
			<b>N/A</b>	Flare Slope LT (%)	N/A
			<b>N/A</b>	Flare Traversable LT?	N/A
			<b>N/A</b>	Flare Type RT	N/A
			<b>N/A</b>	Flare Slope RT (%)	N/A
			<b>N/A</b>	Flare Traversable RT?	N/A
			<b>N/A</b>	DWS Provided?	N/A
<p>Surveyor Notes:</p> <p><b>N/A</b></p>			<b>N/A</b>	DWS Contrast?	N/A
			<b>N/A</b>	DWS Length (in)	N/A
			<b>N/A</b>	DWS Full Width?	N/A
			<b>N/A</b>	DWS Offset (in)	N/A
			<b>N/A</b>	Gutter Ponding?	N/A
			<b>N/A</b>	Gutter X Slope (%)	N/A
			<b>N/A</b>	Gutter Lip Ht (in)	N/A
			<b>N/A</b>	Painted X Walk1?	Yes
			<b>N/A</b>	X Walk 1 Direction	To S
			<b>N/A</b>	X Walk 1 Width (in)	112.5
<p>PROW/ADA:</p> <p><b>Not Found, R304.5.3</b></p>			<b>N/A</b>	X Walk 1 Slope (%)	5.8
			<b>N/A</b>	X Walk 1 X Slope (%)	1.8
			<b>N/A</b>	Ramp inside XWalk1?	Yes
			<b>N/A</b>	Road Slope (%)	N/A
			<b>N/A</b>	Road X Slope (%)	N/A
			<b>N/A</b>	Any Obstructions?	N/A
			<b>N/A</b>	Obstruction Type	
			<b>N/A</b>	Clear Space?	N/A
			<b>N/A</b>	Clear Space to XWalk (in)	N/A
			<b>N/A</b>	Storm Grate/Utility Hazard?	N/A
<p>Total Cost:</p> <p><b>\$ 1850.00</b></p>			<b>N/A</b>	Storm Grate/Utility Type	
			<b>N/A</b>	Surface Condition? (G/P)	Good

