

Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

| | | | | |
|---------------------------|--------------------------------|-------------------------|------------------------|----------------------|
| Intersection ID: 10024955 | Main Street: DISTRICT_SOUTH_DR | Cross Street: N/A | Location: | N |
| ADA ID: 8CA63E67768B | Ramp Type: BlendTrans2 | Initial Pass/Fail: Pass | Overall Compliance: No | Severity Score: 0.25 |

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Possible Solutions:

Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.

Surveyor Notes:

N/A

PROW/ADA:

R304.5.3

Total Cost:

\$ 3200.00

| Compliance | Description | Data | Compliance | Description | Data |
|------------|-----------------------|------|------------|-----------------------------|------|
| N/A | Ramp Length (in) | 88.0 | Yes | BlendTrans Slope (%) | 2.0 |
| Yes | Ramp Width (in) | 96.0 | No | BlendTrans XSlope (%) | 2.7 |
| N/A | Flare Type LT | N/A | N/A | Flare Type RT | N/A |
| N/A | Flare Slope LT (%) | N/A | N/A | Flare Slope RT (%) | N/A |
| N/A | Flare Traversable LT? | N/A | N/A | Flare Traversable RT? | N/A |
| N/A | Landing Length (in) | N/A | Yes | DWS Provided? | Yes |
| N/A | Landing Width (in) | N/A | Yes | DWS Contrast? | Yes |
| N/A | Landing Slope (%) | N/A | Yes | DWS Length (in) | 24.0 |
| N/A | Landing X Slope (%) | N/A | Yes | DWS Full Width? | Yes |
| N/A | Landing Curb? (Y/N) | Yes | Yes | DWS Offset (in) | 0.0 |
| N/A | Shared Landing? | No | | | |
| Yes | Gutter Ponding? | No | Yes | Gutter Slope (%) | 2.6 |
| Yes | Gutter Lip Ht (in) | 0.0 | Yes | Gutter X Slope (%) | 0.2 |
| N/A | Painted X Walk1? | No | N/A | Painted X Walk2? | N/A |
| | X Walk 1 Direction | To S | | X Walk 2 Direction | N/A |
| | X Walk 1 Width (in) | N/A | | X Walk 2 Width (in) | N/A |
| | X Walk 1 Slope (%) | 1.5 | | X Walk 2 Slope (%) | N/A |
| | X Walk 1 X Slope (%) | 1.1 | | X Walk 2 X Slope (%) | N/A |
| N/A | Ramp inside XWalk1? | N/A | N/A | Ramp inside XWalk2? | N/A |
| | Road Slope (%) | 1.1 | | Clear Space? | Yes |
| | Road X Slope (%) | 1.5 | N/A | Clear Space to XWalk (in) | N/A |
| Yes | Any Obstructions? | No | Yes | Storm Grate/Utility Hazard? | No |
| | Obstruction Type | | | Storm Grate/Utility Type | |
| | | | N/A | | N/A |
| | | | Yes | Surface Condition? (G/P) | Good |
| | | | N/A | Curb Slope (%) | 2.5 |

| | |
|-------------------------|-------------------|
| Street 1 Name | DISTRICT SOUTH DR |
| Stop Condition-Street 1 | None |
| Street 2 Name | N/A |
| Stop Condition-Street 2 | N/A |

