# Access Compliance Report
# Public Rights-of-Way
# (Curb Ramps)

| | | | |
|---|---|---|---|
| **Intersection ID: 4441** | **Main Street: GOVERNOR_HUNT_RD** | **Cross Street: MALLARD_CREEK_RD** | **Location: NW** |
| **ADA ID: 8CBA0679084F** | **Ramp Type: Perp** | **Initial Pass/Fail: Fail** | **Overall Compliance: No** | **Severity Score: 13.75** |

## Codes/Mitigation Info/Possible Solution

Possible Solutions:

**Remove & Replace Entire Ramp.**

Surveyor Notes:

**N/A**

PROW/ADA:

**R304.2.2**

| | |
|---|---|
| Street 1 Name | **MALLARD CREEK CHURCH RD** |
| Stop Condition-Street 2 | **Signal** |
| Street 2 Name | **N/A** |
| Stop Condition-Street 1 | **N/A** |

Total Cost: **$ 1850.00**

## Field Measurements/Component Compliance

| Compliance | Description | Data | Compliance | Description | Data |
|---|---|---|---|---|---|
| N/A | Ramp Length (in) | 41.0 | No | Ramp Slope (%) | 11.0 |
| Yes | Ramp Width (in) | 62.0 | Yes | Ramp XSlope (%) | 4.1 |
| N/A | Flare Type LT | N/A | N/A | Flare Type RT | N/A |
| N/A | Flare Slope LT (%) | N/A | N/A | Flare Slope RT (%) | N/A |
| N/A | Flare Traversable LT? | N/A | N/A | Flare Traversable RT? | N/A |
| N/A | Landing Length (in) | N/A | N/A | DWS Provided? | N/A |
| N/A | Landing Width (in) | N/A | N/A | DWS Contrast? | N/A |
| N/A | Landing Slope (%) | N/A | N/A | DWS Length (in) | N/A |
| N/A | Landing X Slope (%) | N/A | N/A | DWS Full Width? | N/A |
| N/A | Landing Curb? (Y/N) | N/A | N/A | DWS Offset (in) | N/A |
| N/A | Shared Landing? | N/A | | | |
| N/A | Gutter Ponding? | N/A | N/A | Gutter Slope (%) | N/A |
| N/A | Gutter Lip Ht (in) | N/A | N/A | Gutter X Slope (%) | N/A |
| N/A | Painted X Walk1? | No | N/A | Painted X Walk2? | N/A |
| | X Walk 1 Direction | To E | | X Walk 2 Direction | N/A |
| N/A | X Walk 1 Width (in) | N/A | N/A | X Walk 2 Width (in) | N/A |
| | X Walk 1 Slope (%) | 5.4 | | X Walk 2 Slope (%) | N/A |
| | X Walk 1 X Slope (%) | 6.8 | | X Walk 2 X Slope (%) | N/A |
| N/A | Ramp inside XWalk1? | N/A | N/A | Ramp inside XWalk2? | N/A |
| | Road Slope (%) | N/A | N/A | Clear Space? | N/A |
| | Road X Slope (%) | N/A | N/A | Clear Space to XWalk (in) | N/A |
| N/A | Any Obstructions? | N/A | N/A | Storm Grate/Utility Hazard? | N/A |
| | Obstruction Type | | | Storm Grate/Utility Type | |
| | | N/A | | | N/A |
| | | | Yes | Surface Condition? (G/P) | Good |