

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 19216 Main Street: RAMA_RD Cross Street: SARDIS_RD Location: SW **Overall Compliance: No ADA ID: 8CEECC1FCD60** Ramp Type: Perp Initial Pass/Fail: Fail **Severity Score:** 12.5

Codes/Mitigation Info/Possible Solution



SARDIS RD Street 1 Name Signal Stop Condition-Street 2 Street 2 Name N/A Stop Condition-Street 1 N/A

OSSIBIE SOIGHOIT	
Possible Solutions:	Co
Remove & Replace Entire Ramp.	N/A
·	Yes
	N/A
	N/A
	N/A
	N/A
Surveyor Notes:	N/A
N/A	N/A
	N/A
	N/A
	N/A
PROW/ADA:	N/A
Not Found, R304.2.2	N/A
	N/A
	N/A
	N/A

A	



Total Cost:



1850.00

Field Measurements/Component Compliance								
Compl	iance Description	Data	Compl	iance	Description	Data		
N/A	Ramp Length (in)	60.0	No	Ramp	Slope (%)	8.4		
Yes	Ramp Width (in)	48.0	Yes	Ramp	XSlope (%)	0.2		
N/A	Flare Type LT	N/A	N/A	Flare	Type RT	N/A		
N/A	Flare Slope LT (%)	N/A	N/A	Flare	Slope RT (%)	N/A		
N/A	Flare Traversable LT?	N/A	N/A	Flare	Traversable RT?	N/A		
N/A	Landing Length (in)	N/A	N/A	DWS	Provided?	N/A		
N/A	Landing Width (in)	N/A	N/A	DWS	Contrast?	N/A		
N/A	Landing Slope (%)	N/A	N/A	DWS	Length (in)	N/A		
N/A	Landing X Slope (%)	N/A	N/A	DWS	Full Width?	N/A		
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS	Offset (in)	N/A		
N/A	Shared Landing?	N/A						
N/A	Gutter Ponding?	N/A	N/A	Gutte	r Slope (%)	N/A		
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutte	r X Slope (%)	N/A		
N/A	Painted X Walk1?	Yes	N/A	Paint	ed X Walk2?	N/A		
	X Walk 1 Direction	To NE		X Wa	lk 2 Direction	N/A		
N/A	X Walk 1 Width (in)	113.0	N/A	X Wa	lk 2 Width (in)	N/A		
	X Walk 1 Slope (%)	2.2		X Wa	lk 2 Slope (%)	N/A		
	X Walk 1 X Slope (%)	0.5		X Wa	lk 2 X Slope (%)	N/A		
N/A	Ramp inside XWalk1?	Yes	N/A	Ram	inside XWalk2?	N/A		
	Road Slope (%)	N/A	N/A	Clear	Space?	N/A		
	Road X Slope (%)	N/A	N/A	Clear	Space to XWalk (in)	N/A		
N/A	Any Obstructions?	N/A	N/A	Storn	n Grate/Utility Hazard?	N/A		
	Obstruction Type			Storn	n Grate/Utility Type			
		N/A				N/A		
			Yes	Surfa	ce Condition? (G/P)	Good		