## cole

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 9945	Main Str	eet: BREWTON DR	Cross	Street <sup>.</sup>	OAKLAWN AV	Location:	NW		
ADA ID: 8D0ADA2EB3A3	ADA ID: 8D0ADA2EB3A3 Ramp Type: PerpDiag		Initial F	Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	21.25
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
	A CONTRACTOR	Possible Solutions:		Compliance Description Data			Comp	Compliance Description D	
		Remove & Replace Curb Ramp	With	N/A	Ramp Length (in)	50.5	No	Ramp Slope (%)	9.3
		Two New Directional Ramps or		No	Ramp Width (in)	47.5	Yes	Ramp XSlope (%)	1.2
		Equivalent.		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
A CONTRACT				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
	1-2-20			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
	6	Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
E.		N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
OLATATIAN AV				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
to when the state of the			N/A	Shared Landing?	N/A				
A MARINE A	and the second	PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
		Not Found, R304.5.1, R304.2.2		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
				N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
					X Walk 1 Direction	To S		X Walk 2 Direction	To SE
				N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	OAKLAWN AV	_			X Walk 1 Slope (%)	4.9		X Walk 2 Slope (%)	4.4
Stop Condition-Street 2	None				X Walk 1 X Slope (%)	3.4		X Walk 2 X Slope (%)	0.9
Street 2 Name	BREWTON DR			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	StopSign				Road Slope (%)	3.0	N/A	Clear Space?	N/A
					Road X Slope (%)	3.9	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$	3200.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A

Yes Surface Condition? (G/P)

Good





