

# Access Compliance Report

## Public Rights-of-Way

### (Curb Ramps)

Intersection ID: 8660	Main Street: GENERAL_COMMERCE_DR	Cross Street: INDUSTRIAL_CENTER_CR	Location: SW
ADA ID: 8D7221009497	Ramp Type: Combination1	Initial Pass/Fail: Pass	Overall Compliance: No
Codes/Mitigation Info/Possible Solution		Field Measurements/Component Compliance	
Severity Score: 19.25			



Possible Solutions:

**Remove & Replace Entire Ramp.  
Remove & Replace Sidewalk.**

Surveyor Notes:

**GTR LIP 1.0", LT RP < 5%**

PROW/ADA:

**Not Found, R304.5.3, R304.2.1,  
R304.2.2-Perp, R304.3.2-Para,  
R302.7, R302.7.2**

Street 1 Name	None
Stop Condition-Street 1	GENERAL COMMERC DR
Street 2 Name	N/A
Stop Condition-Street 2	N/A

Total Cost: \$ 2200.00

Compliance	Description	Data	Compliance	Description	Data
N/A	Ramp Length LT (in)	54.0	N/A	Ramp Length RT (in)	58.0
Yes	Ramp Width LT (in)	59.0	Yes	Ramp Width RT (in)	60.5
Yes	Ramp Slope LT (%)	4.8	Yes	Ramp Slope RT (%)	8.1
No	Ramp XSlope LT (%)	3.2	No	Ramp XSlope RT (%)	2.2
N/A	Ramp Length (in)	27.0	Yes	Ramp Slope (%)	8.0
Yes	Ramp Width (in)	48.0	Yes	Ramp XSlope (%)	0.3
N/A	Flare Type LT	Sloped	N/A	Flare Type RT	Sloped
Yes	Flare Slope LT (%)	6.3	Yes	Flare Slope RT (%)	4.8
N/A	Flare Traversable LT?	Yes	N/A	Flare Traversable RT?	Yes
No	Landing Length (in)	35.0	Yes	DWS Provided?	Yes
No	Landing Width (in)	46.5	Yes	DWS Contrast?	Yes
No	Landing Slope (%)	2.4	Yes	DWS Length (in)	25.5
No	Landing X Slope (%)	3.3	Yes	DWS Full Width?	Yes
N/A	Landing Curb? (Y/N)	No	Yes	DWS Offset (in)	0.0
N/A	Shared Landing?	No			
No	Gutter Ponding?	Yes	Yes	Gutter Slope (%)	1.6
No	Gutter Lip Ht (in)	1.0	Yes	Gutter X Slope (%)	0.6
N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
	X Walk 1 Direction	To N		X Walk 2 Direction	N/A
	X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
	X Walk 1 Slope (%)	1.2		X Walk 2 Slope (%)	N/A
	X Walk 1 X Slope (%)	0.3		X Walk 2 X Slope (%)	N/A
N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
	Road Slope (%)	N/A		Clear Space?	Yes
	Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
			Yes	Any Obstruction?	No
				Obstruction Type	N/A
			Yes	Storm Grate/Utility Hazard?	No
				Storm Grate/Utility Type	N/A
			Yes	Surface Condition? (G/P)	Good
				Curb Slope (%)	10.0

