## cole

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



				_						
Intersection ID: 18405	Main Street: ADDISON_DR		Cross Street: LINCREST_PL					Location:	w	
ADA ID: 8D847439A536	Ramp Type: PerpDiag		Initial Pass/Fail: Fail Overall Compl			Compliar	iance: No Severity Score:		22.5	
Codes/Mitigation Info/Possible Solution					Field Measurements/Component Compliance					
		Possible Solutions:	C	Compliance Description		Data Compliance Des			Data	
		Remove & Replace Curb Ramp Wi	ith N	/ <b>A</b>	Ramp Length (in)	60.0	No	Ramp Slope (%)	11.7	
		Two New Directional Ramps or Equivalent.	 N		Ramp Width (in)	47.0	No	Ramp XSlope (%)	3.4	
			N	/ <b>A</b>	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
			N	/ <b>A</b>	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
Contraction of the second			N	/ <b>A</b>	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
			N	/ <b>A</b>	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
L			N	/ <b>A</b>	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
		N/A	N	/ <b>A</b>	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
		PROW/ADA:	N	/ <b>A</b>	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
E.			N	/ <b>A</b>	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
			N	/ <b>A</b>	Shared Landing?	N/A				
States States			N	/ <b>A</b>	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
The second secon	and allow the	R304.5.1, R304.2.2, R304.5.3	N	/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
	Carl March B.	1004.011, 1004.2.2, 1004.0.0	N	/ <b>A</b>	Painted X Walk1?	No	N/A	Painted X Walk2?	No	
					X Walk 1 Direction	To SE		X Walk 2 Direction	To NE	
			N	/ <b>A</b>	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A	
Street 1 Name	LINCREST PL				X Walk 1 Slope (%)	0.6		X Walk 2 Slope (%)	3.0	
Stop Condition-Street 2	StopSign				X Walk 1 X Slope (%)	3.3		X Walk 2 X Slope (%)	2.1	
Street 2 Name	ADDISON DR		N	/ <b>A</b>	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
Stop Condition-Street 1	None				Road Slope (%)	0.6	N/A	Clear Space?	N/A	
					Road X Slope (%)	3.9	N/A	Clear Space to XWalk (in)	N/A	
			Ν	/ <b>A</b>	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A	
		Total Cost: \$ 32	00.00		Obstruction Type			Storm Grate/Utility Type		
						N/A			N/A	

Yes Surface Condition? (G/P) Good

