## cole

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 18769	Main St	reet: BARCLAY_DOWNS_DR	Cross	Stroot				Location:	w	
					Cross Street: RUNNYMEDE_LN					
ADA ID: 8D9A0414B5C3	DA ID: 8D9A0414B5C3 Ramp Type: Perp			Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	25	
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance						
		Possible Solutions:		Compliance Description Data C			Comp	Compliance Description Data		
1 Million and		Remove & Replace Entire Ramp	).	N/A	Ramp Length (in)	54.0	Yes	Ramp Slope (%)	5.6	
	Part and			Yes	Ramp Width (in)	48.0	No	Ramp XSlope (%)	11.0	
A CONTRACTOR	in 1			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
A RUM	The state			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
ALL	6 6			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
LAN CONTRACTOR	5 <u>6</u>			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
	<u></u>	Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
en e	101	N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
	5			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
5	6.			N/A	Shared Landing?	N/A				
	ALA STATE	PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
State State	11 Mars	Not Found, R304.5.3		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
	and and	·		N/A	Painted X Walk1?	Yes	N/A	Painted X Walk2?	N/A	
SAGAMORE RD					X Walk 1 Direction	To NE		X Walk 2 Direction	N/A	
6.				N/A	X Walk 1 Width (in)	114.0	N/A	X Walk 2 Width (in)	N/A	
Street 1 Name	RUNNYMEDE LN				X Walk 1 Slope (%)	5.6		X Walk 2 Slope (%)	N/A	
Stop Condition-Street 2	Signal				X Walk 1 X Slope (%)	7.1		X Walk 2 X Slope (%)	N/A	
Street 2 Name	N/A			N/A	Ramp inside XWalk1?	Yes	N/A	Ramp inside XWalk2?	N/A	
Stop Condition-Street 1	N/A				Road Slope (%)	N/A	N/A	Clear Space?	N/A	
					Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A	
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A	
		Total Cost: \$	1850.00		Obstruction Type			Storm Grate/Utility Type		
						N/A			N/A	

s Surface Condition? (G/P)

Good

