

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 14200 Main Street: CLARICE_AV Cross Street: E_7TH_ST Location: Ε

Overall Compliance: No ADA ID: 8DB8BB4C9788 Ramp Type: Perp Initial Pass/Fail: Fail **Severity Score:** 12.5

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



CLARICE AV Street 1 Name Stop Condition-Street 2 StopSign Street 2 Name N/A Stop Condition-Street 1 N/A

Possible Solutions:	<u>c</u>
Remove & Replace Entire Ramp.	N
	Ye
	N/
	N
	N
	N
Surveyor Notes:	N
N/A	N
	N
	N
	N
PROW/ADA:	N
Not Found, R304.5.3	N
,	N
	N

		N/A
		N/A
nd, R304.5.3		N/A
	\$ 1850.00	N/A

Total Cost:	\$	1850.00

Comp	liance Description	Data	Comp	liance Desc	ription	Data
N/A	Ramp Length (in)	56.0	Yes	Ramp Slope	e (%)	7.5
Yes	Ramp Width (in)	48.0	No	Ramp XSlop	pe (%)	5.5
N/A	Flare Type LT	N/A	N/A	Flare Type F	RT	N/A
N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope	RT (%)	N/A
N/A	Flare Traversable LT?	N/A	N/A	Flare Traver	sable RT?	N/A
N/A	Landing Length (in)	N/A	N/A	DWS Provid	led?	N/A
N/A	Landing Width (in)	N/A	N/A	DWS Contra	ast?	N/A
N/A	Landing Slope (%)	N/A	N/A	DWS Lengtl	h (in)	N/A
N/A	Landing X Slope (%)	N/A	N/A	DWS Full W	/idth?	N/A
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset	(in)	N/A
N/A	Shared Landing?	N/A				
N/A	Gutter Ponding?	N/A	N/A	Gutter Slope	∈ (%)	N/A
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slo	ppe (%)	N/A
N/A	Painted X Walk1?	No	N/A	Painted X W	/alk2?	N/A
	X Walk 1 Direction	To NW		X Walk 2 Di	rection	N/A
N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 W	idth (in)	N/A
	X Walk 1 Slope (%)	4.4		X Walk 2 Sl	ope (%)	N/A
	X Walk 1 X Slope (%)	1.6		X Walk 2 X	Slope (%)	N/A
N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside	e XWalk2?	N/A
	Road Slope (%)	N/A	N/A	Clear Space	e?	N/A
	Road X Slope (%)	N/A	N/A	Clear Space	e to XWalk (in)	N/A
N/A	Any Obstructions?	N/A	N/A	Storm Grate	e/Utility Hazard?	N/A
	Obstruction Type			Storm Grate	e/Utility Type	
		N/A				N/A
			Yes	Surface Cor	ndition? (G/P)	Good





