


Intersection ID: 42552	Main Street: ESTHER_LN	Cross Street: LUNDY_LN	Location:	S
ADA ID: 8DF138D6AE54	Ramp Type: Perpendicular	Initial Pass/Fail: Fail	Overall Compliance: No	Severity Score: 8.75

Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance						
	Possible Solutions:		Compliance			Compliance			
	<b>Remove &amp; Replace Entire Ramp.</b>		Description			Description			
			Data			Data			
			Compliance			Compliance			
			Description			Description			
			Data			Data			
			Compliance			Compliance			
			Description			Description			
			Data			Data			
			Compliance			Compliance			
Surveyor Notes:									
<b>N/A</b>									
PROW/ADA:									
<b>R304.5.1</b>									
Street 1 Name		<b>ESTHER LN</b>							
Stop Condition-Street 2		<b>StopSign</b>							
Street 2 Name		<b>N/A</b>							
Stop Condition-Street 1		<b>N/A</b>							
Total Cost:		<b>\$ 1850.00</b>							

Compliance			Description			Data			Compliance			Description			Data		
N/A	Ramp Length (in)	49.0	Yes	Ramp Slope (%)	8.2	No	Ramp Width (in)	42.0	Yes	Ramp XSlope (%)	0.1	N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	N/A	Shared Landing?	N/A				N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A	N/A	Gutter X Slope (%)	N/A	N/A	Gutter X Slope (%)	N/A
N/A	X Walk 1 Direction	To N		X Walk 2 Direction	N/A	N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A	N/A	X Walk 1 Slope (%)	3.2		X Walk 2 Width (in)	N/A
N/A	X Walk 1 Slope (%)	0.9		X Walk 2 Slope (%)	N/A	N/A	X Walk 1 X Slope (%)	0.9		X Walk 2 X Slope (%)	N/A	N/A	X Walk 1 X Slope (%)	0.9		X Walk 2 X Slope (%)	N/A
N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	N/A	Road Slope (%)	N/A	N/A	Clear Space?	N/A	N/A	Ramp inside XWalk1?	N/A	N/A	Clear Space?	N/A
N/A	Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A	N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A	N/A	Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
N/A	Obstruction Type		N/A	Storm Grate/Utility Type	N/A	N/A				Storm Grate/Utility Type	N/A	N/A	Obstruction Type			Storm Grate/Utility Type	N/A
			Yes	Surface Condition? (G/P)	Good												

