

Intersection ID: 27478		Main Street: BALLANTYNE MEADOWS DR		Cross Street: BLUE CEDAR LN		Location:		NE			
ADA ID: 8E265AE2DC2C		Ramp Type: Perpendicular Diagonal		Initial Pass/Fail: Fail		Overall Compliance: No		Severity Score: 26.25			
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance							
				Possible Solutions:		Compliance		Description		Data	
				Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.		N/A		Ramp Length (in)		45.0	
Surveyor Notes:				N/A		Yes		Ramp Width (in)		48.0	
						N/A		Flare Type LT		N/A	
PROW/ADA:				R304.2.2, R304.5.3		N/A		Flare Slope LT (%)		N/A	
						N/A		Flare Traversable LT?		N/A	
Total Cost:				\$ 3200.00		N/A		Landing Length (in)		N/A	
						N/A		Landing Width (in)		N/A	
Street 1 Name				BLUE CEDAR LN		N/A		Landing Slope (%)		N/A	
						N/A		Landing X Slope (%)		N/A	
Stop Condition-Street 2				StopSign		N/A		Landing Curb? (Y/N)		N/A	
						N/A		Shared Landing?		N/A	
Street 2 Name				BALLANTYNE MEADOWS DR		N/A		Gutter Ponding?		N/A	
						N/A		Gutter Lip Ht (in)		N/A	
Stop Condition-Street 1				None		N/A		Painted X Walk1?		No	
						N/A		X Walk 1 Direction		To NW	
Total Cost:				\$ 3200.00		N/A		X Walk 1 Width (in)		N/A	
						N/A		X Walk 1 Slope (%)		3.7	
Street 1 Name				BLUE CEDAR LN		N/A		X Walk 1 X Slope (%)		0.5	
						N/A		Ramp inside XWalk1?		N/A	
Stop Condition-Street 2				StopSign		N/A		Road Slope (%)		4.8	
						N/A		Road X Slope (%)		2.2	
Street 2 Name				BALLANTYNE MEADOWS DR		N/A		Any Obstructions?		N/A	
						N/A		Obstruction Type			
Stop Condition-Street 1				None		N/A		Storm Grate/Utility Hazard?		N/A	
						N/A		Storm Grate/Utility Type			
Total Cost:				\$ 3200.00		N/A		Surface Condition? (G/P)		Good	
						N/A					

