## cole

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 51356 Main Street: BRENTMOOR_DR						Cross Street: PEARL_ST				S
ADA ID: 8E6979678CE2	Ramp Type: Combination1							Location: ance: No Severity Score:		22.5
Codes/Mitigation Info/Possible Solution					Field Measurements/Component Compliance					
the second	Possible Solutions:			Compliance Description				bliance Description	Data	
2 2 3	A March 1	Remove & Replace Enti	re Rar	np.	N/A	Ramp Length LT (in			Ramp Length RT (in)	70.0
	1STR In				No	Ramp Width LT (in)	47.5		Ramp Width RT (in)	49.0
the BIA					Yes	Ramp Slope LT (%)		Yes	Ramp Slope RT (%)	6.3
					No	Ramp XSlope LT (%		No	Ramp XSlope RT (%)	4.4
G					N/A	Ramp Length (in)	49.0		Ramp Slope (%)	9.1
the state of the s	and a start				No	Ramp Width (in)	47.0		Ramp XSlope (%)	0.1
6.	A PARTING	Surveyor Notes:			N/A	Flare Type LT	N/A		Flare Type RT	N/A
the second secon	1000 P	N/A			N/A	Flare Slope LT (%)	N/A		Flare Slope RT (%)	N/A
A to the second	103				N/A	Flare Traversable L			Flare Traversable RT?	N/A
	the main of				N/A	Landing Length (in)	N/A		DWS Provided?	N/A
	1 13				N/A	Landing Width (in)	N/A		DWS Contrast?	N/A
E10 8	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	PROW/ADA:			N/A	Landing Slope (%)	N/A		DWS Length (in)	N/A
	- Ali	Not Found, R304.5.1, R	304.5.	1,	N/A	Landing X Slope (%	·		DWS Full Width?	N/A
	A Martin	R304.2.2, R304.5.3			N/A	Landing Curb? (Y/N			DWS Offset (in)	N/A
- RM	12 1 Jana				N/A	Shared Landing?	N/A			
					N/A	Gutter Ponding?	N/A		Gutter Slope (%)	N/A
Street 1 Name	None				N/A	Gutter Lip Ht (in)	N/A		Gutter X Slope (%)	N/A
Stop Condition-Street 1	BRENTMOOR DR				N/A	Painted X Walk1?	No		Painted X Walk2?	N/A
Street 2 Name	N/A					X Walk 1 Direction	To NE		X Walk 2 Direction	N/A
Stop Condition-Street 2	N/A					X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
						X Walk 1 Slope (%)			X Walk 2 Slope (%)	N/A
			•			X Walk 1 X Slope (%			X Walk 2 X Slope (%)	N/A
		Total Cost:	\$	1800.00	N/A	Ramp inside XWalk			Ramp inside XWalk2?	N/A
						Road Slope (%)	N/A		Clear Space?	N/A
						Road X Slope (%)	N/A		Clear Space to XWalk (in)	N/A
				in in	目山	A har		N/A	Any Obstruction?	N/A
									Obstruction Type	
				RA				<b> </b>		N/A
	1 and		Carl Carl					N/A	Storm Grate/Utility Hazard?	N/A
			the second	~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~					Storm Grate/Utility Type	
		The second			1-	(				N/A
	La the la		/		1	the second se		Yes	Surface Condition? (G/P)	Good
		1		- /				I	Curb Slope (%)	18.5