


Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 9575	Main Street: CATALINA_AV	Cross Street: WINSTON_ST	Location: SW
ADA ID: 8E84CEF75288	Ramp Type: Combination2	Initial Pass/Fail: Fail	Overall Compliance: No
			Severity Score: 58.75

Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance					
	Possible Solutions:		Compliance	Description	Data	Compliance	Description	Data
	Remove & Replace Entire Ramp.		N/A	Ramp Length LT (in)	25.0	N/A	Ramp Length RT (in)	25.0
			N/A	Ramp Width LT (in)	39.0	No	Ramp Width RT (in)	39.0
			N/A	Ramp Slope LT (%)	3.1	Yes	Ramp Slope RT (%)	6.6
			N/A	Ramp XSlope LT (%)	7.6	No	Ramp XSlope RT (%)	6.9
			N/A	Ramp Length (in)	53.0	No	Ramp Slope (%)	12.1
			Yes	Ramp Width (in)	49.5	No	Ramp XSlope (%)	3.7
	Surveyor Notes:		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
	LT RP < 5%		N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
PROW/ADA: R304.5.1, R304.2.2, R304.5.3		N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
		N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
		N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
		N/A	Shared Landing?	N/A				
		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
		N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A	
					X Walk 1 Direction	To NW		X Walk 2 Direction
			X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A	
			X Walk 1 Slope (%)	3.4		X Walk 2 Slope (%)	N/A	
			X Walk 1 X Slope (%)	3.6		X Walk 2 X Slope (%)	N/A	
		N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
			Road Slope (%)	N/A		Clear Space?	N/A	
			Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A	
					N/A	Any Obstruction?	N/A	
						Obstruction Type	N/A	
					N/A	Storm Grate/Utility Hazard?	N/A	
						Storm Grate/Utility Type	N/A	
		Yes	Surface Condition? (G/P)	Good				
			Curb Slope (%)	N/A				

Street 1 Name

YieldSign

Stop Condition-Street 1

CATALINA AV

Street 2 Name

N/A

Stop Condition-Street 2

N/A

Total Cost:

\$

1600.00

