## cole

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 12653	Main Stre	Main Street: N_MYERS_ST				E_8TH_ST	Location: S			
ADA ID: 8E8A06302FF4	Ramp Ty	Ramp Type: Combination2Diag			Initial Pass/Fail: Fail Overall Complian			nce: No Severity Score: 0		0
Codes/Mitigation Info/Possible Solution					Field Measurements/Component Compliance					
	A Dest	Possible Solutions:			Compliance Description		Data Compliance Description			Data
		Remove & Replace	Curb Ramp With		N/A	Ramp Length LT (in)	N/A	N/A	Ramp Length RT (in)	55.0
		Two New Directional Ramps or Equivalent.				Ramp Width LT (in)	N/A	No	Ramp Width RT (in)	36.0
					N/A	Ramp Slope LT (%)	N/A	Yes	Ramp Slope RT (%)	6.7
					N/A	Ramp XSlope LT (%)	N/A	No	Ramp XSlope RT (%)	4.3
					N/A	Ramp Length (in)	25.0	Yes	Ramp Slope (%)	7.0
bits &					Yes	Ramp Width (in)	49.0	No	Ramp XSlope (%)	4.2
	A VIL	Surveyor Notes:			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
	and the	N/A			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
C C C C C C C C C C C C C C C C C C C					N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
	144				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
					N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
		PROW/ADA:			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
	Not Found, R304.5.1, R304.5.3			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
				N/A	Shared Landing?	N/A				
the state of the				N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
Street 1 Name	None				N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
Stop Condition-Street 1	E 8TH ST				N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
Street 2 Name	StopSign					X Walk 1 Direction	To NE		X Walk 2 Direction	To NW
Stop Condition-Street 2	N MYERS ST					X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
						X Walk 1 Slope (%)	2.4		X Walk 2 Slope (%)	3.4
						X Walk 1 X Slope (%)	4.7		X Walk 2 X Slope (%)	2.5
		Total Cost:	\$	3200.00	N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
						Road Slope (%)	1.9		Clear Space?	N/A
						Road X Slope (%)	2.6	N/A	Clear Space to XWalk (in)	N/A
			1	15.0	× Kar			N/A	Any Obstruction?	N/A
				ALL TRADAD					Obstruction Type	
\$\$			TIT							N/A
1		and have				115		N/A	Storm Grate/Utility Hazard?	N/A
	A State of the second	- 1 / - Alton			and the			I		IN/A

 
 Yes
 Surface Condition? (G/P)
 Good Curb Slope (%)



