

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 2895	on ID: 2895 Main Street: CREEK_BREEZE_RD Cross Street: RIDGE_RD							Location:	w
ADA ID: 8EA038F347A4				itial Pass/Fail: Fail Overall Compliance: No					
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
Possible Solutions:									
			A/;+b	N/A	Ramp Length (in)	46.0	No	Ramp Slope (%)	<u>Data</u> 13.4
		Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.	with	No	Ramp Width (in)	44.0	No	Ramp XSlope (%)	6.6
				N/A	Flare Type LT	0 N/A	N/A	Flare Type RT	N/A
				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
KIDGE R				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
Brown of the				N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
		N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
Contraction of Contra		N/A		N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
and the second		2		N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
				N/A	Shared Landing?	N/A		DWG Oliset (III)	11/4
		PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
				N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
The second of the		R304.5.1, R304.2.2, R304.5.3		N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A No
				N/A	X Walk 1 Direction	To SE	IN/A	X Walk 2 Direction	To NE
T-FIFTY Dock				N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name CREEK BREEZE RD				N/A		1.5	N/A		7.8
Stop Condition-Street 2					X Walk 1 Slope (%)	1.5 8.4		X Walk 2 Slope (%)	7.o 1.4
Stop Condition-Street 2 Street 2 Name	StopSign RIDGE RD			N/A	X Walk 1 X Slope (%) Ramp inside XWalk1?	0.4 N/A	N/A	X Walk 2 X Slope (%) Ramp inside XWalk2?	1.4 N/A
				N/A	•		N/A	•	N/A N/A
Stop Condition-Street 1	None				Road Slope (%)	6.4		Clear Space?	
				NI/A	Road X Slope (%)	5.6	N/A	Clear Space to XWalk (in)	N/A
		Total Coatt	2200.00	N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$	3200.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A

Yes Surface Condition? (G/P)

Good





