

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 10040	Main Street: HAZEL_ST			Cross Street: TUCKASEEGEE_RD				Location:	SW	
ADA ID: 8EA632F79FEC	EC Ramp Type: Directional1			Initial Pass/Fail: Fail Overall Compliance: No			o Severity Score:	21.25		
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance						
	1	Possible Solutions:		Compliance Description			Data Compliance Description Data			
STA X		Remove & Replace Entire Ram	<b>)</b> .	N/A	Ramp Length (in)	87.0	N/A	Grade Break?	N/A	
				No	Ramp Width (in)	47.5	N/A	Grade Break Slope (%)	0.0	
	and a			No	Ramp Slope (%)	10.4	N/A	Grade Break XSlope (%)	0.0	
e.	and the			Yes	Ramp XSlope (%)	1.8				
THE BALL				N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
6.				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	0.0	
		Surveyor Notes:		N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
		N/A		N/A	Landing Length (in)	0.0	N/A	DWS Provided?	N/A	
				N/A	Landing Width (in)	0.0	N/A	DWS Contrast?	N/A	
	The Contract			N/A	Landing Slope (%)	0.0	N/A	DWS Length (in)	N/A	
	All the let			N/A	Landing X Slope (%)	0.0	N/A	DWS Full Width?	N/A	
		PROW/ADA:		N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset LT (in)	N/A	
The second second	16 M 1 1	R304.5.1, R304.2.2		N/A	Shared Landing?	N/A	N/A	DWS Offset RT (in)	N/A	
all and a series of the series	A SALA			N/A	Gutter Ponding?	0.0	N/A	Gutter Slope (%)	N/A	
Contraction 1 and 1	14 P			N/A	Gutter Lip Ht (in)	0.0	N/A	Gutter X Slope (%)	N/A	
				N/A	Painted X Walk1?	No		Road Slope (%)	3.6	
Street 1 Name	HAZEL ST				X Walk 1 Direction	To E		Road X Slope (%)	3.3	
Stop Condition-Street 1	StopSign				X Walk 1 Width (in)	N/A		Clear Space?	N/A	
Street 2 Name	N/A				X Walk 1 Slope (%)	3.6	N/A	Clear Space to XWalk (in)	N/A	
Stop Condition-Street 2	N/A				X Walk 1 X Slope (%)	3.3	N/A	Storm Grate/Utility Hazard?	N/A	
				N/A	Ramp inside XWalk1?	N/A		Storm Grate/Utility Type		
				N/A	Any Obstructions?	N/A			N/A	
		Total Cost: \$	1600.00		Obstruction Type		Yes	Surface Condition? (G/P)	Good	
						N/A	N/A	Curb Slope (%)	4.1	

