

## **Access Compliance Report Public Rights-of-Way** (Curb Ramps)



Intersection ID: 14943 Main Street: REMOUNT RD **Cross Street: DUNAVANT ST** Location:

ADA ID: 8ED0361A4D3E Ramp Type: Perpendicular Diagonal Initial Pass/Fail: Fail **Overall Compliance: No Severity Score:** 12.5

## **Codes/Mitigation Info/Possible Solution**

## **Field Measurements/Component Compliance**



Street 1 Name Stop Condition-Street 2 Street 2 Name Stop Condition-Street 1 **DUNAVANT ST** StopSign **REMOUNT RD** None Possible Solutions: Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent. Surveyor Notes: N/A PROW/ADA: Not Found, R304.2.2

Total Cost: 3200.00

Compl	iance Description	Data	ta Compliance Description		Data
N/A	Ramp Length (in)	93.0	No	Ramp Slope (%)	8.5
Yes	Ramp Width (in)	73.0	Yes	Ramp XSlope (%)	0.8
N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
N/A	Shared Landing?	N/A			
N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
	X Walk 1 Direction	To NW		X Walk 2 Direction	To SW
N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
	X Walk 1 Slope (%)	0.9		X Walk 2 Slope (%)	0.3
	X Walk 1 X Slope (%)	0.3		X Walk 2 X Slope (%)	0.5
N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
	Road Slope (%)	0.3	N/A	Clear Space?	N/A
	Road X Slope (%)	0.7	N/A	Clear Space to XWalk (in)	N/A

N/A

N/A

N/A

Yes

Storm Grate/Utility Type

Surface Condition? (G/P)

Storm Grate/Utility Hazard?

N/A

N/A

N/A

Good







N/A

Any Obstructions?

**Obstruction Type**