cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



								Landar	
Intersection ID: 27102 Main S		treet: ANDREWS_LINKS_ST		Cross Street: STEWART_RIDGE_ST				Location:	NE
ADA ID: 8F026FCD3164 Ramp Ty		Type: Perpendicular Diagonal Init		al Pass/Fail: Fail Overall Complian			nce: N	o Severity Score:	46.25
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
	STEWART_RIDGE_ST	Possible Solutions:		Compliance Description		Data	Data Compliance Description		Data
		Remove & Replace Curb Ram	p With	N/A	Ramp Length (in)	96.5	No	Ramp Slope (%)	10.4
A A A A A A A A A A A A A A A A A A A		Two New Directional Ramps or Equivalent.	r	No	Ramp Width (in)	44.5	No	Ramp XSlope (%)	10.3
				N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
		N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
		Sec.		N/A	Shared Landing?	N/A			
	A Se	PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
and a start of the		R304.5.1, R304.2.2, R304.5.3		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
		, ,		N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
					X Walk 1 Direction	To W		X Walk 2 Direction	To S
				N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name ANDRE	EWS LINKS ST				X Walk 1 Slope (%)	6.2		X Walk 2 Slope (%)	1.4
Stop Condition-Street 2	None				X Walk 1 X Slope (%)	3.6		X Walk 2 X Slope (%)	7.1
Street 2 Name STEWA	ART RIDGE ST			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	StopSign				Road Slope (%)	8.1	N/A	Clear Space?	N/A
					Road X Slope (%)	0.8	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$	3200.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A

Yes Surface Condition? (G/P)

Good

