

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

50.0

71.0

12.7

3.4

5.4

5.1

N/A

N/A

N/A

N/A

N/A

8.5

Intersection ID: 50203 Main Street: WEDDINGTON_RD Cross Street: COLTSVIEW_LN Location: NW
ADA ID: 8F11654E5AC1 Ramp Type: Combination1 Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 37.5

Compliance Description

Ramp Length LT (in)

Ramp Width LT (in)

Ramp Slope LT (%)

Ramp Length (in)

Ramp Width (in)

Flare Slope LT (%)

Landing Length (in)

Landing Width (in)

Flare Traversable LT?

Flare Type LT

Ramp XSlope LT (%)

N/A

Yes

Yes

No

N/A

Yes

N/A

N/A

N/A

N/A

N/A

N/A

N/A N/A N/A N/A

N/A

N/A

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

N/A

Yes

No

No

Yes

No

N/A

N/A

N/A

N/A

N/A N/A

Compliance Description

Ramp Length RT (in)

Ramp Width RT (in)

Ramp Slope RT (%)

Ramp XSlope RT (%)

Ramp Slope (%)

Ramp XSlope (%)

Flare Slope RT (%)

DWS Provided?

DWS Contrast?

Curb Slope (%)

Flare Traversable RT?

Flare Type RT

Data

39.0

71.0

5.2

2.1

96.0

48.0

N/A

N/A

N/A

N/A



Street 1 Name
Stop Condition-Street 1
WEDDINGTON RD
Street 2 Name
N/A
Stop Condition-Street 2
N/A

Possible Solutions:

Remove & Replace Entire Ramp.

Surveyor Notes:

N/A

PROW/ADA:

Not Found, R304.5.3, R304.3.2



Total Cost:



1800.00

Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
Shared Landing?	N/A			
Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
X Walk 1 Direction	To E		X Walk 2 Direction	N/A
X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
X Walk 1 Slope (%)	1.0		X Walk 2 Slope (%)	N/A
X Walk 1 X Slope (%)	2.5		X Walk 2 X Slope (%)	N/A
Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Road Slope (%)	2.5		Clear Space?	N/A
Road X Slope (%)	1.0	N/A	Clear Space to XWalk (in)	N/A
		N/A	Any Obstruction?	N/A
			Obstruction Type	
				N/A
		N/A	Storm Grate/Utility Hazard?	N/A
		l	Storm Grate/Utility Type	1071
				N/A
		Yes	Surface Condition? (G/P)	Good