

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

40.0

59.0

5.9

3.1

9.7

4.0

N/A

N/A

0.0

Good

Main Street: NORRIS AV **Cross Street: NEWLAND RD** Location: Intersection ID: 8938 Initial Pass/Fail: Fail **Overall Compliance: No** Severity Score: 48.75 ADA ID: 8F2BD631AFF1

Ramp Type: Combination1

Field Measurements/Component Compliance

N/A

Yes

Yes

No

N/A

Compliance Description

Ramp Length RT (in)

Ramp Width RT (in)

Ramp Slope RT (%)

Ramp Slope (%)

Flare Type RT

Ramp XSlope (%)

Ramp XSlope RT (%)

Surface Condition? (G/P)

Curb Slope (%)

Data

52.0

59.0

4.9

2.7

N/A

61.0 No

31.5 No

Ramp Length LT (in)

Ramp Width LT (in)

Ramp Slope LT (%)

Ramp Length (in)

Ramp Width (in)

Flare Type LT

Ramp XSlope LT (%)



Street 1 Name	StopSign
Stop Condition-Street 1	NORRIS AV
Street 2 Name	N/A
Stop Condition-Street 2	N/A

Codes/Mitigation Info/Possible Solution Possible Solutions: Compliance Description Remove & Replace Entire Ramp. N/A Yes Yes No N/A No Surveyor Notes: N/A N/A LT RP < 5% PROW/ADA: R304.5.1, R304.2.2, R304.5.3 N/



Total Cost:



1800.00

N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
N/A	Shared Landing?	N/A			
N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
	X Walk 1 Direction	To N		X Walk 2 Direction	N/A
	X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
	X Walk 1 Slope (%)	1.7		X Walk 2 Slope (%)	N/A
	X Walk 1 X Slope (%)	2.2		X Walk 2 X Slope (%)	N/A
N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
	Road Slope (%)	N/A		Clear Space?	N/A
	Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
			N/A	Any Obstruction?	N/A
主。非				Obstruction Type	
					N/A
			N/A	Storm Grate/Utility Hazard?	N/A
				Storm Grate/Utility Type	

Yes