

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 16392	Main St	Main Street: QUEENS_RD_WEST Ramp Type: Directional1			Cross Street: WELLESLEY_AV Initial Pass/Fail: Fail Overall Compliance: No			Location:	SW	
ADA ID: 8F305FED0EE7	Ramp T							o Severity Score:	12.5	
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance						
	A AND THE	Possible Solutions:	Compliance Description			Data Compliance Description			Data	
States and the states	State / Dask	Remove & Replace Entire Ramp	_	N/A	Ramp Length (in)	57.5	N/A	Grade Break?	N/A	
No. 30	State 1 10 16 14			Yes	Ramp Width (in)	75.0	N/A	Grade Break Slope (%)	0.0	
N Parts				No	Ramp Slope (%)	8.9	N/A	Grade Break XSlope (%)	0.0	
	1/ Alas	8		Yes	Ramp XSlope (%)	1.8				
L. C.	5. / S. R.			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
UEL A	L. Mart			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	0.0	
6	Man A State	Surveyor Notes:		N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
	A B	N/A		N/A	Landing Length (in)	0.0	N/A	DWS Provided?	N/A	
	a d.			N/A	Landing Width (in)	0.0	N/A	DWS Contrast?	N/A	
	<u>6</u> 6			N/A	Landing Slope (%)	0.0	N/A	DWS Length (in)	N/A	
	MAR YON	é		N/A	Landing X Slope (%)	0.0	N/A	DWS Full Width?	N/A	
	1 10 day 40 1 3	PROW/ADA:		N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset LT (in)	N/A	
	is no	R304.2.2		N/A	Shared Landing?	N/A	N/A	DWS Offset RT (in)	N/A	
				N/A	Gutter Ponding?	0.0	N/A	Gutter Slope (%)	N/A	
				N/A	Gutter Lip Ht (in)	0.0	N/A	Gutter X Slope (%)	N/A	
	S SAME DARK	8		N/A	Painted X Walk1?	No		Road Slope (%)	1.4	
Street 1 Name	QUEENS RD WEST	_			X Walk 1 Direction	To NW		Road X Slope (%)	2.0	
Stop Condition-Street 1	None				X Walk 1 Width (in)	N/A		Clear Space?	N/A	
Street 2 Name	N/A				X Walk 1 Slope (%)	1.4	N/A	Clear Space to XWalk (in)	N/A	
Stop Condition-Street 2	N/A				X Walk 1 X Slope (%)	2.0	N/A	Storm Grate/Utility Hazard?	N/A	
				N/A	Ramp inside XWalk1?	N/A		Storm Grate/Utility Type		
				N/A	Any Obstructions?	N/A			N/A	
		Total Cost: \$	1600.00		Obstruction Type		Yes	Surface Condition? (G/P)	Good	
						N/A	N/A	Curb Slope (%)	4.4	

