cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 23720 Main St		reet: ELIZABETH_LN		Cross	Street:	PINEVILLE-MATTHEW	Location:	NW			
ADA ID: 8F5B55CB132F Ramp Type: Perpend		ype: Perpendicular Diagonal	ndicular Diagonal Initial			I Pass/Fail: Fail Overall Complianc			o Severity Score:	10	
Codes/Mitigation Info/Possible Solution						Field Measurements/Component Compliance					
Possible Solutions:					Compliance Description Data Compliance Description					Data	
and the second								1			
		Remove & Replace Curb R			N/A	Ramp Length (in)	70.0		Ramp Slope (%)	5.5	
		Two New Directional Ramps Equivalent.		r	No	Ramp Width (in)	47.5		Ramp XSlope (%)	2.1	
12 · · · ·					N/A	Flare Type LT	N/A		Flare Type RT	N/A	
United Internet					N/A	Flare Slope LT (%)	N/A		Flare Slope RT (%)	N/A	
					N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
the second second					N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
		Surveyor Notes:			N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
and the second	N/A			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A		
FINEVILLE ANATUMENTE RD					N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
					N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
					N/A	Shared Landing?	N/A				
					N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
The second second	Not Found, R304.5.1, R304	1.5.3		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A		
Not Found, R304.5.1, R304.5					N/A	Painted X Walk1?	Yes	N/A	Painted X Walk2?	Yes	
						X Walk 1 Direction	To S		X Walk 2 Direction	To E	
					N/A	X Walk 1 Width (in)	101.0	N/A	X Walk 2 Width (in)	106.0	
Street 1 Name	PINEVILLE-MATTHEWS RD					X Walk 1 Slope (%)	1.1		X Walk 2 Slope (%)	0.2	
Stop Condition-Street 2	Signal					X Walk 1 X Slope (%)	2.0		X Walk 2 X Slope (%)	1.9	
Street 2 Name	SCHOONER LN				N/A	Ramp inside XWalk1?	Yes	N/A	Ramp inside XWalk2?	Yes	
Stop Condition-Street 1	Signal					Road Slope (%)	2.0	N/A	Clear Space?	N/A	
	·					Road X Slope (%)	3.5	N/A	Clear Space to XWalk (in)	N/A	
					N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A	
		Total Cost:	\$	3200.00		Obstruction Type			Storm Grate/Utility Type		
			•				N/A			N/A	
								Yes	Surface Condition? (G/P)	Good	
								162		3000	

