

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 10162 Main Street: E SUGAR CREEK RD **Cross Street: THE PLAZA** Location: SW Ramp Type: BlendTrans2 Initial Pass/Fail: Pass **Overall Compliance: No Severity Score:** 10 ADA ID: 8FFA462C5819

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Street 1 Name Stop Condition-Street 1 Street 2 Name Stop Condition-Street 2 **E SUGAR CREEK RD** Signal **THE PLAZA** Signal

Remove & Replace Curb Ramp With Two New Directional Ramps or **Equivalent. Restripe Crosswalk(s)** To Provide Clear space.

Surveyor Notes:

N/A

PROW/ADA:

Not Found, R305.1.4, R305.2, R302.7.2

Total Cost: 3700.00

				!	
Compli	iance Description	Data	Comp	liance Description	Data
N/A	Ramp Length (in)	136.0	Yes	BlendTrans Slope (%)	2.7
Yes	Ramp Width (in)	68.0	Yes	BlendTrans XSlope (%)	1.3
N/A	Flare Type LT	None	N/A	Flare Type RT	None
N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
N/A	Landing Length (in)	N/A	Yes	DWS Provided?	Yes
N/A	Landing Width (in)	N/A	Yes	DWS Contrast?	Yes
N/A	Landing Slope (%)	N/A	Yes	DWS Length (in)	25.5
N/A	Landing X Slope (%)	N/A	No	DWS Full Width?	No
N/A	Landing Curb? (Y/N)	Yes	No	DWS Offset (in)	36.0
N/A	Shared Landing?	No			
Yes	Gutter Ponding?	No	Yes	Gutter Slope (%)	2.2
No	Gutter Lip Ht (in)	0.5	Yes	Gutter X Slope (%)	1.9
N/A	Painted X Walk1?	Yes	N/A	Painted X Walk2?	Yes
	X Walk 1 Direction	To NE		X Walk 2 Direction	To NW
	X Walk 1 Width (in)	115.5		X Walk 2 Width (in)	139.0
	X Walk 1 Slope (%)	2.9		X Walk 2 Slope (%)	4.6
	X Walk 1 X Slope (%)	6.0		X Walk 2 X Slope (%)	1.0
Yes	Ramp inside XWalk1?	Yes	Yes	Ramp inside XWalk2?	Yes
	Road Slope (%)	3.5		Clear Space?	Yes
	Road X Slope (%)	6.1	No	Clear Space to XWalk (in)	38.5
Yes	Any Obstructions?	No	Yes	Storm Grate/Utility Hazard?	No
	Obstruction Type			Storm Grate/Utility Type	
		N/A	l		N/A
			Yes	Surface Condition? (G/P)	Good
			No	Curb Slope (%)	13.4





