## cole

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: N/A Main Street: YORKMONT_RD				Street.	N/A	Location:	NE		
				Cross Street: N/A					
ADA ID: 9029F39C3E33	DA ID: 9029F39C3E33 Ramp Type: PerpDiag			Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	16.25
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
		Possible Solutions:		Compliance Description		Data	Data Compliance Description		Data
· · · ·		Remove & Replace Curb Ramp V	Vith	N/A	Ramp Length (in)	40.0	Yes	Ramp Slope (%)	5.3
		Two New Directional Ramps or Equivalent.		Yes	Ramp Width (in)	48.0	No	Ramp XSlope (%)	3.9
				N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
and a set				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
6	A. Well			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
	1. 187 L			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
	* /	Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
A C		N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
A CONTRACT OF				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
	S ME			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
	E NO			N/A	Shared Landing?	N/A			
St. In		PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
A MAR	Not Found, R304.5.3, R302.7		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
				N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
the second second second second				X Walk 1 Direction	To NW		X Walk 2 Direction	To W	
				N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	ENTRANCE				X Walk 1 Slope (%)	2.1		X Walk 2 Slope (%)	0.3
Stop Condition-Street 2	StopSign				X Walk 1 X Slope (%)	0.4		X Walk 2 X Slope (%)	1.3
Street 2 Name	YORKMONT RD			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	None				Road Slope (%)	1.6	N/A	Clear Space?	N/A
					Road X Slope (%)	1.5	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$ 3	3200.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A

No Surface Condition? (G/P)

Poor

