

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 3384 Main Street: KATELYN\_DR Cross Street: THISTLEDOWN\_CT Location: S

ADA ID: 909A45F7A293 Ramp Type: Directional1 Initial Pass/Fail: Fail Overall Compliance: No. Severity Score: 12.5

Initial Pass/Fail: Fail **Overall Compliance: No Severity Score:** 12.5 ADA ID: 909A45E7A293 Ramp Type: Directional1 **Codes/Mitigation Info/Possible Solution** Field Measurements/Component Compliance Possible Solutions: Compliance Description Data Compliance Description Data N/A Grade Break? N/A Ramp Length (in) 50.0 N/A Remove & Replace Entire Ramp. 48.0 N/A Yes Ramp Width (in) Grade Break Slope (%) 0.0 N/A Yes Ramp Slope (%) 6.3 Grade Break XSlope (%) 0.0 No Ramp XSlope (%) 5.4 N/A Flare Type LT N/A N/A Flare Type RT N/A N/A Flare Slope LT (%) N/A N/A Flare Slope RT (%) 0.0 Surveyor Notes: N/A Flare Traversable LT? N/A N/A Flare Traversable RT? N/A N/A 0.0 N/A **DWS Provided?** N/A Landing Length (in) N/A **DWS Contrast?** N/A Landing Width (in) 0.0 N/A N/A N/A Landing Slope (%) 0.0 N/A DWS Length (in) N/A N/A N/A Landing X Slope (%) 0.0 DWS Full Width? N/A PROW/ADA: N/A Landing Curb? (Y/N) N/A N/A DWS Offset LT (in) N/A R304.5.3 N/A Shared Landing? N/A N/A DWS Offset RT (in) N/A N/A **Gutter Ponding?** 0.0 N/A Gutter Slope (%) N/A N/A Gutter Lip Ht (in) 0.0 N/A Gutter X Slope (%) N/A N/A Painted X Walk1? No Road Slope (%) 1.6 THISTLEDOWN CT To NE Street 1 Name X Walk 1 Direction Road X Slope (%) 0.4 Stop Condition-Street 1 StopSign X Walk 1 Width (in) N/A Clear Space? N/A N/A 1.6 N/A Street 2 Name X Walk 1 Slope (%) Clear Space to XWalk (in) N/A Stop Condition-Street 2 N/A X Walk 1 X Slope (%) 0.4 N/A Storm Grate/Utility Hazard? N/A N/A Ramp inside XWalk1? N/A Storm Grate/Utility Type N/A N/A Any Obstructions? N/A Total Cost: **Obstruction Type** Surface Condition? (G/P) 1600.00 Yes Good N/A N/A Curb Slope (%) 11.5





