cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: N/A	Main Street: HICKORY_GROVE_RD				Cross Street: SUSAN_DR				Location:	NE
ADA ID: 90A3E5368A23	Ramp Ty	Ramp Type: Combination1				ail: Fail Overall C	ce: N	o Severity Score:	37.5	
Codes/M	litigation Info	/Possible Solution				Field Measure	ments/C	ompo	nent Compliance	
		Possible Solutions:			Compliance Description		Data Compliance Description			Data
		Remove & Replace	Entire Ran	np.	N/A	Ramp Length LT (in)	64.0	N/A	Ramp Length RT (in)	39.0
				.6.	Yes	Ramp Width LT (in)	73.0	Yes	Ramp Width RT (in)	75.0
					Yes	Ramp Slope LT (%)	2.5	No	Ramp Slope RT (%)	11.8
	18. /				No	Ramp XSlope LT (%)	2.8	Yes	Ramp XSlope RT (%)	0.5
	NO. 11				N/A	Ramp Length (in)	73.0	No	Ramp Slope (%)	9.0
					Yes	Ramp Width (in)	48.0	No	Ramp XSlope (%)	7.5
		Surveyor Notes:			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
		N/A			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
					N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
The second secon	1/5/				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
Contract Cont	/// .				N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
Intercon		PROW/ADA:			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
		Not Found, R304.2.2	R304.2.2. R304.5.3.		N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
	R304.3.2			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
1 Same				N/A	Shared Landing?	N/A				
				N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
Street 1 Name	None	-			N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
Stop Condition-Street 1	SUSAN DR				N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
Street 2 Name	N/A					X Walk 1 Direction	To W		X Walk 2 Direction	N/A
Stop Condition-Street 2	N/A					X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
						X Walk 1 Slope (%)	2.4		X Walk 2 Slope (%)	R9146
						X Walk 1 X Slope (%)	4.9		X Walk 2 X Slope (%)	N/A
		Total Cost:	\$	1800.00	N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
						Road Slope (%)	N/A		Clear Space?	N/A
						Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
				10 - C				N/A	Any Obstruction?	N/A
	Lat Contain								Obstruction Type	
	C Prestance		1							N/A
where the second second second					-	1		N/A	Storm Grate/Utility Hazard?	

N/A Storm Grate/Utility Hazard? N/A Storm Grate/Utility Type N/A Yes Surface Condition? (G/P) Good Curb Slope (%) 11.6