## cole

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



		• • •		~-			
Intersection ID: 28929	Main Street: WADE_ARDREY_RD		et: CAMPBELL_HALL_O	Location:	NW		
ADA ID: 90CB0F26DA87	Ramp Type: PerpDiag	Initial Pass	/Fail: Fail Overall	Compliand	ce: No Severity Score:	42.5	
Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance				
	Possible Solutions:	Co	Compliance Description Data		Compliance Description	Data	
	Remove & Replace Curb Ramp V	Nith N/A	Ramp Length (in)	94.0	Yes Ramp Slope (%)	5.4	
	Two New Directional Ramps or	No	Ramp Width (in)	32.0	No Ramp XSlope (%)	8.4	
	Equivalent.	N/A	Flare Type LT	N/A	N/A Flare Type RT	N/A	
	A COMPANY OF THE OWNER	N/A	Flare Slope LT (%)	N/A	N/A Flare Slope RT (%)	N/A	
	and the statement of th	N/A	Flare Traversable LT?	N/A	N/A Flare Traversable RT?	N/A	
		N/A	Landing Length (in)	N/A	N/A DWS Provided?	N/A	
	Surveyor Notes:	N/A	Landing Width (in)	N/A	N/A DWS Contrast?	N/A	
	N/A	N/A	Landing Slope (%)	N/A	N/A DWS Length (in)	N/A	
A 20 12 6	1	N/A	Landing X Slope (%)	N/A	N/A DWS Full Width?	N/A	
ALLONE G. G.		N/A	Landing Curb? (Y/N)	N/A	N/A DWS Offset (in)	N/A	
MUDIan G. C.	Las T	N/A	Shared Landing?	N/A			
	PROW/ADA:	N/A	Gutter Ponding?	N/A	N/A Gutter Slope (%)	N/A	
	Not Found, R304.5.1, R304.5.3	N/A	Gutter Lip Ht (in)	N/A	N/A Gutter X Slope (%)	N/A	
		N/A	Painted X Walk1?	No	N/A Painted X Walk2?	No	
			X Walk 1 Direction	To SW	X Walk 2 Direction	To SE	
		N/A	X Walk 1 Width (in)	N/A	N/A X Walk 2 Width (in)	N/A	
Street 1 Name WADE AR	RDREY RD		X Walk 1 Slope (%)	4.2	X Walk 2 Slope (%)	1.5	
Stop Condition-Street 2	None		X Walk 1 X Slope (%)	4.6	X Walk 2 X Slope (%)	5.5	
Street 2 Name CAMPBELL	- HALL CT	N/A	Ramp inside XWalk1?	N/A	N/A Ramp inside XWalk2?	N/A	
Stop Condition-Street 1	StopSign		Road Slope (%)	10.2	N/A Clear Space?	N/A	
			Road X Slope (%)	1.3	N/A Clear Space to XWalk (in)	N/A	
		N/A	Any Obstructions?	N/A	N/A Storm Grate/Utility Hazard?	N/A	
	Total Cost: \$ 3	200.00	Obstruction Type		Storm Grate/Utility Type		
				N/A		N/A	

Yes Surface Condition? (G/P)

Good

